

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

1996 MAZDA 323 F (CB) OEM Service and Repair Workshop Manual

Go to manual page

STEP	INSPECTION	RESULTS	ACTION
11	VERIFY DTC TROUBLESHOOTING COMPLETED Caution • Connect the negative battery terminal before connecting the current sensor connector. If the current sensor connected first, the PCM may mistakenly recognize a signal from the current sensor	Yes	Repeat the inspection from Step 1.
	 and learn the battery condition incorrectly. Always reconnect all disconnected connectors. Clear the DTC from the PCM memory using the M-MDS. (See CLEARING DTC [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) Start the engine. Perform the DTC Reading Procedure. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) Is the same Pending DTC present? 	No	Go to the next step.
12	VERIFY AFTER REPAIR PROCEDURE • Perform the "AFTER REPAIR PROCEDURE". (See AFTER REPAIR PROCEDURE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) DTC troubleshooting completed.

STEP	INSPECTION	RESULTS	ACTION
2	line repair information availability.	Yes	Perform repair or diagnosis according to the available repair information. • If the vehicle is not repaired, go to the next step.
	• Is any related repair information available?	No	Go to the next step.
3	VERIFY RELATED PENDING CODE AND/OR DTC • Switch the ignition off, then ON (engine off). • Perform the Pending Trouble Code Access Procedure and DTC Reading Procedure. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) • Are any other PENDING CODEs and/or DTCs present?	Yes	Go to the applicable PENDING CODE or DTC inspection. (See DTC TABLE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)
		No	Go to the next step.
• Switch the ign bisconnect the connector.		Yes	Repair or replace the connector and/or terminals, then go to Step 8.
	Inspect for poor connection (such as amaged/pulled-out pins, corrosion). Is there any malfunction?	No	Go to the next step.

DTC PO4DB:00 [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))]

SM3511177

id0102s985700

Note

• To determine the malfunctioning part, proceed with the diagnostics from "Function Inspection Using M-MDS".


Details On DTCs

DESCRIPTION	Positive crankcase ventilation (PCV) System: Excessive flow detected			
	Determination conditions	The estimated PCV flow volume is exceeds threshold.		
		 Fuel injection control: During fuel cut at deceleration *1 Barometric pressure: 70.75 kPa {0.7215 kgf/cm², 10.27 psi} or more *1 Engine speed: 3,000 rpm or less *1 The following DTCs are not detected: 		
		— TP sensor: P0122:00, P0123:00, P0222:00, P0223:00 and P0638:00 — ECT sensor: P0117:00 and P0118:00		
		— MAP sensor: P0107:00 and P0108:00		
		— MAF sensor: P0100:00 and U060F:00		
		— BARO sensor: P2226:00, P2228:00 and P2229:00		
		— IAT sensor No.1: P0110:00		
	Preconditions	— IAT sensor No.2: P0097:00 and P0098:00		
DETECTION CONDITION		— Purge solenoid valve: P0443:00		
		— Intake CMP sensor: P0340:00		
		— Exhaust CMP sensor: P0365:00		
		— Electric variable valve timing control system: P0010:00,		
		P0011:00 and P0012:00 and P2138:00		
		— Hydraulic variable valve timing control system: P0014:00,		
		P0015:00, P2090:00 and P2091:00		
		— Throttle valve actuator control: P2101:00, P2107:00, P2109:00		
		P2112:00, P2119:00 and P2135:00		
	D : 1	*1: Standard can be verified by displaying PIDs using M-MDS		
	Drive cycle	• 2		
	Self test type	• CMDTC self test		
	Sensor used	• MAF sensor • MAP sensor		
FAIL-SAFE FUNCTION	Not applicable			
EHICLE STATUS WHEN DTCs ARE OUTPUT	• Not applicable			
	• Blow-by gas passa	age between PCV valve and intake manifold malfunction		
POSSIBLE CAUSE	 — Poor connection of blow-by gas hose between PCV valve and intake manifold • A non-genuine air cleaner or air cleaner cover installed • PCV valve malfunction (stuck open) 			

PCM malfunction

STEP	INSPECTION		ACTION
4	PURPOSE: VERIFY AFTER REPAIR PROCEDURE • Perform the "AFTER REPAIR PROCEDURE". (See AFTER REPAIR PROCEDURE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)
		No	DTC troubleshooting completed.





Diagnostic Procedure

STEP	INSPECTION	RESULTS	ACTION
	RECORD VEHICLE STATUS AT TIME OF DTC DETECTION TO UTILIZE WITH REPEATABILITY VERIFICATION		
1	 Note Recording can be facilitated using the screen capture function of the PC. Record the FREEZE FRAME DATA/snapshot 	-	Go to the next step.
	data on the repair order.		
2	VERIFY RELATED REPAIR INFORMATION AVAILABILITY • Verify related Service Bulletins and/or on-line repair information availability. • Is any related repair information available?	Yes	Perform repair or diagnosis according to the available repair information. • If the vehicle is not repaired, go to the next step.
		No	Go to the next step.

DTC P0182:00 [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))]


SM3511153

id0102s914740

DTC P0182:00	Fuel temperature sensor circuit low input
	• The PCM monitors the fuel temperature sensor signal. If the PCM detects that the fuel temperature sensor voltage at the PCM terminal 1AA is below 0.11 V for 5 s, the PCM determines that the fuel temperature sensor circuit has a malfunction.
	MONITORING CONDITIONS — Battery voltage: 8 V or more Diagnostic support note • This is a continuous monitor (other). • The check engine light does not illuminate. • FREEZE FRAME DATA is not available. • Snapshot data is available. • DTC is stored in the PCM memory.
FAIL-SAFE FUNCTION	• Not applicable
POSSIBLE CAUSE	 Low fuel pressure sensor/fuel temperature sensor connector or terminals malfunction Fuel temperature sensor malfunction Short to ground in wiring harness between low fuel pressure sensor/fuel temperature sensor terminal E and PCM terminal 1AA PCM connector or terminals malfunction Fuel temperature sensor signal circuit and ground circuit are shorted to each other PCM malfunction



STEP	INSPECTION	RESULTS	ACTION
			Disconnect the PCM connector and inspect the wiring harness for short to ground. • If the short to ground circuit could be detected in the wiring harness:
			 Refer to the wiring diagram and verify whether or not there is a common connector between low fuel pressure sensor/fuel temperature sensor terminal E and PCM terminal 1AA.
INSPECT FUEL TEMPERATURE SENSOR SIGNAL CIRCUIT FOR SHORT TO GROUND • Verify that the low fuel pressure sensor/fuel temperature sensor connector is disconnected. • Switch the ignition off. • Inspect for continuity between low fuel pressure sensor/fuel temperature sensor terminal E (wiring harness-side) and body ground. • Is there continuity?	Yes	If there is a common connector: • Determine the malfunctioning part by inspecting the common connector and the terminal for corrosion, damage, or pin disconnection, and the common wiring harness for a short to ground. • Repair or replace the malfunctioning part. If there is no common connector: • Repair or replace the wiring harness which has a short to ground. • If the short to ground circuit could not be detected in the wiring harness: — Replace the PCM (short to ground in the PCM internal circuit). (See PCM	
			REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].) Go to Step 9.
		No	Go to the next step.
6	INSPECT PCM CONNECTOR CONDITION • Disconnect the PCM connector. • Inspect for poor connection (such as	Yes	Repair or replace the connector and/or terminals, then go to Step 9.
	damaged/pulled-out pins, corrosion). • Is there any malfunction?	No	Go to the next step.
7	INSPECT FUEL TEMPERATURE SENSOR SIGNAL CIRCUIT AND GROUND CIRCUIT FOR SHORT TO EACH OTHER • Verify that the low fuel pressure sensor/fuel temperature sensor and PCM connectors are disconnected. • Inspect for continuity between low fuel pressure sensor/fuel temperature sensor terminals E and C (wiring harness-side). • Is there continuity?	Yes	Refer to the wiring diagram and verify whether or not there is a common connector between the following terminals: • Low fuel pressure sensor/fuel temperature sensor terminal E-PCM terminal 1AA • Low fuel pressure sensor/fuel temperature sensor terminal C-PCM terminal 1BG If there is a common connector: • Determine the malfunctioning part by inspecting the common connector and the terminal for corrosion, damage, or pin disconnection, and the common wiring harness for a short to each other. • Repair or replace the malfunctioning part. If there is no common connector: • Repair or replace the wiring harness which has a short to each other. Go to Step 9.
		No	Go to the next step.





Diagnostic Procedure

STEP	INSPECTION	RESULTS	ACTION
	RECORD VEHICLE STATUS AT TIME OF DTC DETECTION TO UTILIZE WITH REPEATABILITY VERIFICATION		
	Note		
1	 Recording can be facilitated using the screen capture function of the PC. Record the snapshot data on the repair order. 	_	Go to the next step.
2	VERIFY RELATED REPAIR INFORMATION AVAILABILITY • Verify related Service Bulletins and/or on-line repair information availability.	Yes	Perform repair or diagnosis according to the available repair information. • If the vehicle is not repaired, go to the next step.
	 Is any related repair information available? 	No	Go to the next step.

DTC P0192:00 [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))]

SM2896660

id0102s914770

DTC P0192:00	Fuel pressure sensor circuit low input
DETECTION CONDITION	Until 2021MY • If the input voltage at the PCM terminal 1W is less than 0.66 V for 5 s, the PCM determines that the fuel pressure sensor circuit is low. 2022MY • If the input voltage at the PCM terminal 1W is less than 0.51 V for 5 s, the PCM determines that the fuel pressure sensor circuit is low. Diagnostic support note • This is a continuous monitor (CCM). • The check engine light illuminates if the PCM detects the above malfunction condition during the first drive cycle. • FREEZE FRAME DATA/Snapshot data is available. • DTC is stored in the PCM memory.
FAIL-SAFE FUNCTION	Stops high pressure fuel pump control Limits intake air amount
POSSIBLE CAUSE	 Fuel pressure sensor connector or terminals malfunction PCM connector or terminals malfunction Short to ground in wiring harness between the following terminals: Fuel pressure sensor terminal E-PCM terminal 1K Fuel pressure sensor terminal C-PCM terminal 1W Fuel pressure sensor signal circuit and ground circuit are shorted to each other Fuel pressure sensor malfunction High pressure fuel pump malfunction PCM malfunction