

# Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2003 MAZDA B Series / Bravo Dual Cab OEM Service and Repair Workshop Manual

Go to manual page

# Diagnostic Procedure

STEP	INSPECTION	RESULTS	ACTION
1	INSPECT VEHICLE CONDITION FOR EFFECT ON MALFUNCTION • Verify how the customer drives the vehicle by asking the customer the following:  — Engine speed is high and remains high for continuous long periods like when climbing a long, steep grade. • Is the engine generating excessive heat when driven?	Yes	Explain to the customer that the vehicle is normal and give them advice how to use vehicle and provide a specific example of the conditions in which the engine overheats.
		No	Go to the next step.
2	VERIFY PCM DTC  • Retrieve PCM DTCs using the M-MDS. (See ON-BOARD  DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)  • Are any DTCs present?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)
		No	Go to the next step.
	DETERMINE IF MALFUNCTION CAUSE IS A/C SYSTEM OR	Yes	Go to the next step.
3	OTHER • Start the engine and run it at	No	Perform the symptom troubleshooting "A/C IS ALWAYS ON OR A/C COMPRESSOR RUNS CONTINUOUSLY".  (See A/C IS ALWAYS ON OR A/C COMPRESSOR RUNS CONTINUOUSLY [FULL-AUTO AIR CONDITIONER].)  (See A/C IS ALWAYS ON OR A/C COMPRESSOR RUNS CONTINUOUSLY [MANUAL AIR CONDITIONER].)
		Yes	Go to the next step.
INSPECT ECT SENSOR SIGNAL  • Access the ECT PID using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)  • Compare the ECT PID and low		No	Inspect the ECT sensor. (See ENGINE COOLANT TEMPERATURE (ECT) SENSOR INSPECTION [SKYACTIV-G (WITHOUT EGR COOLER)].) (See ENGINE COOLANT TEMPERATURE (ECT) SENSOR INSPECTION [SKYACTIV-G (WITH EGR COOLER)].) • If there is any malfunction:  — Replace the ECT sensor. (See ENGINE COOLANT TEMPERATURE (ECT) SENSOR REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].) • If there is no malfunction:  — Perform the instrument cluster symptom troubleshooting "LOW ENGINE COOLANT TEMPERATURE INDICATOR LIGHT/HIGH ENGINE COOLANT TEMPERATURE WARNING LIGHT ILLUMINATES OR FLASHES CONTINUOUSLY". (See LOW ENGINE COOLANT TEMPERATURE INDICATOR LIGHT/HIGH ENGINE COOLANT TEMPERATURE WARNING LIGHT WARNING LIGHT ILLUMINATES OR FLASHES CONTINUOUSLY [INSTRUMENT CLUSTER].)

	STEP	INSPECTION	RESULTS	ACTION	
Verify the test results.  • If normal, return to the diagnostic index to service any additional symptoms. (See S [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)  • If the malfunction remains, inspect the related Service Bulletins and/or On-line Rep repair or diagnosis.		)].)			
		<ul> <li>If the vehicle is repaired, troubleshooting is completed.</li> <li>If the vehicle is not repaired or additional diagnostic information is not available, reprogram the PCM if a later calibration is available. Retest.</li> </ul>			



	STEP	INSPECTION	RESULTS	ACTION	
Verify the test results.  • If normal, return to the diagnostic index to service any additional symptoms. (See SYMPTOM DIAGNO [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)  • If the malfunction remains, inspect the related Service Bulletins and/or On-line Repair Information a repair or diagnosis.			)].)		
		<ul> <li>If the vehicle is repaired, troubleshooting is completed.</li> <li>If the vehicle is not repaired or additional diagnostic information is not available, reprogram the PCM if a later calibration is available. Retest.</li> </ul>			



Item (definition)	Unit/Condition	Definition	Condition/Specification (Reference)
APP1	%	APP sensor No.1	<ul> <li>Accelerator pedal released: Approx. 15%</li> <li>Accelerator pedal depressed: Approx. 90.58%</li> </ul>
APP1 APP sensor V		AFF Selisor No.1	<ul> <li>Accelerator pedal released: Approx. 0.75 V</li> <li>Accelerator pedal depressed: Approx. 4.52 V</li> </ul>
ADDO	%	ADD server No. 2	<ul><li>Accelerator pedal released: Approx. 7.45%</li><li>Accelerator pedal depressed: Approx. 45.49%</li></ul>
APP2	V	APP sensor No.2	<ul> <li>Accelerator pedal released: Approx. 0.38 V</li> <li>Accelerator pedal depressed: Approx. 2.26 V</li> </ul>
	°C, °F		Displays ECT
ECT	V	Engine coolant temperature	• ECT is 20 °C {68 °F}: Approx. 3.10 V • ECT is 40 °C {104 °F}: Approx. 2.16 V • ECT is 60 °C {140 °F}: Approx. 1.40 V • ECT is 80 °C {176 °F}: Approx. 0.87 V • ECT is 100 °C {212 °F}: Approx. 0.54 V
	KPa {MPA}, mBar {BAR}, psi, in H20		Displays fuel pressure
FUEL_PRES	V	Fuel pressure	Idle (ECT 80 °C {176 °F}) • Fuel pressure is 10 MPa {102 kgf/cm $^2$ , 1450 psi}: Approx 1.4 V
	°C, °F		• Displays IAT (No.1)
IAT	V	IAT sensor No.1 voltage	• IAT is 20 °C {68 °F}: Approx. 2.70 V • IAT is 40 °C {104 °F}: Approx. 1.80 V • IAT is 60 °C {140 °F}: Approx. 1.20 V
LOAD	%	Engine load	<ul> <li>Idle (after warm up): Approx. 16.07%</li> <li>Racing (engine speed is 2,000 rpm): Approx. 13.33%</li> <li>Racing (engine speed is 4,000 rpm): Approx. 15.29%</li> </ul>
LONGFT1	%	Long term fuel trim	<ul> <li>Idle (after warm up): Approx3.9%</li> <li>Racing (engine speed is 2,000 rpm): Approx0.78%</li> <li>Racing (engine speed is 4,000 rpm): Approx0.78%</li> </ul>
	g/Sec		Displays MAF
MAF	V	Mass air flow	<ul> <li>Ignition switched ON (engine off) (MAF: 0.00 g/s {0 lb/min}): Approx. 1.69 V (ECT is 53 °C {127 °F})</li> <li>Idle (after warm up) (MAF: 2.50 g/s {0.331 lb/min}): Approx. 1.89 V (ECT is 93 °C {199 °F})</li> <li>Racing (engine speed is 2,000 rpm) (MAF: 3.80 g/s {0.503 lb/min}): Approx. 2.02 V (ECT is 95 °C {203 °F})</li> </ul>
МАР	KPa {MPA}, mBar {BAR}, psi, in H20	Manifold absolute pressure	Displays MAP
MAP_V	V	MAP sensor voltage	• Ignition switched ON (engine off) (MAP: 100 kPa {1.02 kgf/cm <sup>2</sup> , 14.5 psi}): Approx. 4.04 V • Idle (after warm up) (MAP: 35 kPa {0.36 kgf/cm <sup>2</sup> , 5.1 psi}): Approx. 1.40 V • Racing (engine speed is 2,000 rpm) (MAP: 26 kPa {0.27 kgf/cm <sup>2</sup> , 3.8 psi}): Approx. 1.01 V
02\$11	μΑ	A/F sensor	• Idle (after warm up): Approx39 µA • Deceleration fuel cut (accelerator pedal released from engine speed of 4,000 rpm or more): Approx. 3.84 mA
02S12	V	HO2S	• Idle (after warm up): 0−1.0 V • Deceleration fuel cut (accelerator pedal released from engine speed of 4,000 rpm or more): Approx. 0 V
RPM	RPM	Engine speed	Displays engine speed
SHRTFT1	%	Short term fuel trim	<ul> <li>Idle (after warm up): Approx. 2.34%</li> <li>Racing (engine speed is 2,000 rpm): Approx. 3.9%</li> <li>Racing (engine speed is 4,000 rpm): Approx. 1.56%</li> </ul>
TP_REL	%	Throttle position signal (relative value)	<ul><li>Accelerator pedal released: Approx. 12%</li><li>Accelerator pedal depressed: Approx. 82%</li></ul>
			· · · · · · · · · · · · · · · · · · ·

NSPECT EXHAUST SYSTEM FOR LEAKAGE   Visually inspect for exhaust gas leakage from exhaust manifold.   No Go to the inspection results.   No Go to the next step.	STEP	INSPECTION	RESULTS	ACTION
INSPECT FUEL PRESSURE (HIGH-SIDE)  Start the engine and warm it up completely.  Access the FUEL_PRES PID using the M-MDS at idle. (See ON-BOARD DIAGNOSTIC TEST (PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)).)  Is the FUEL_PRES PID value approx. 10 MPa (102 kgf/cm², 1,450 psi)?  INSPECTION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)  Is the FUEL_PRES PID value approx. 10 MPa (102 kgf/cm², 1,450 psi)?  INSPECTION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)  Is the FUEL_PRES PID value approx. 10 MPa (102 kgf/cm², 1,450 psi)?  If there is any malfunction:  — Repair or replace the malfunctioning part according to the inspection results.  If there is no malfunction:  — Go to Step 12.  Higher than 10 MPa (102 kgf/cm², 1,450 psi):  Go to the next step.  Go to Step 12.  Higher than 10 MPa (102 kgf/cm², 1,450 psi):	8	• Visually inspect for exhaust gas leakage	Yes	
JUSTIC FUEL PRESSURE (HIGH-SIDE)  Start the engine and warm it up completely.  Access the FUEL_PRES PID using the M-MDS at idle. (See ON-BOARD DIAGNOSTIC TEST (PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))).  Is the FUEL_PRES PID value approx. 10 MPa (102 kgf/cm², 1,450 psi)?  No.  See HIGH FUEL PRESSURE (SWITH CYLINDER DEACTIVATION)].)  Is the FUEL_PRES PID value approx. 10 MPa (102 kgf/cm², 1,450 psi)?  Lower than 10 MPa (102 kgf/cm², 1,450 psi):  - Fuel pleakage at the fuel line and fuel injector  - Fuel pleaking DEACTIVATION Inspection, Inspection (See ENGINE CONTROL SYSTEM OPERATION)  INSPECTION (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)).)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION (SKYACTIV-G (WITH EGR COOLER)).)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION (SKYACTIV-G (WITH EGR COOLER)).)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION (SKYACTIV-G (WITH EGR COOLER)).)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION (SKYACTIV-G (WITH EGR COOLER)).)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure sensor (See FUEL PRESSURE SENSOR INSPECTION)  - Fuel pressure s			No	Go to the next step.
• Inspect the following:  - Fuel leakage at the fuel line and fuel injector  - Fuel pump  • Perform the Fuel Pump (Low-pressure Side) Operation Inspection. (See ENGINE CONTROL SYSTEM OPERATION INSPECTION [SKYACTIV-6 2.5 (WITH CYLINDER DEACTIVATION)].)  • Access the FUEL_PRES PID using the M-MDS at idle. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-6 2.5 (WITH CYLINDER DEACTIVATION)].)  • Is the FUEL_PRES PID value approx. 10 MPa (102 kgf/cm², 1,450 psi)?  No (See HIGH FUEL PRESSURE SENSOR INSPECTION [SKYACTIV-6 (WITH EGR COOLER)].)  (See HIGH FUEL PRESSURE SENSOR INSPECTION [SKYACTIV-6 (WITH EGR COOLER)].)  - High pressure fuel pump (See HIGH PRESSURE FUEL PUMP INSPECTION [SKYACTIV-6 2.5 (WITH CYLINDER DEACTIVATION)].)  • If there is any malfunction:  - Repair or replace the malfunctioning part according to the inspection results.  • If there is no malfunction:  - Go to Step 12.  Higher than 10 MPa (102 kgf/cm², 1,450 psi):  • Go to the next step.			Yes	Go to Step 13.
DETERMINE IE MALIEUNICTION CALICE IC	9	Start the engine and warm it up completely.  Access the FUEL_PRES PID using the M-MDS at idle. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)  Is the FUEL_PRES PID value approx. 10 MPa	No	<ul> <li>Inspect the following:         <ul> <li>Fuel leakage at the fuel line and fuel injector</li> <li>Fuel pump</li> </ul> </li> <li>Perform the Fuel Pump (Low-pressure Side) Operation             Inspection. (See ENGINE             CONTROL SYSTEM OPERATION             INSPECTION [SKYACTIV-G 2.5</li></ul>
FUEL PRESSURE SENSOR OR HIGH  PRESSURE FUEL PUMP  In the wabiele person performance.	10	PRESSURE FUEL PUMP		·
on is the venicle acceleration performance No No Go to Step 12.		<ul> <li>Is the vehicle acceleration performance normal?</li> </ul>		Go to Step 12.
INSPECT FUEL PRESSURE SENSOR  • Inspect the fuel pressure sensor. (See FUEL PRESSURE SENSOR INSPECTION [SKYACTIV-G (WITHOUT EGR COOLER)].) (See HIGH FUEL PRESSURE SENSOR INSPECTION [SKYACTIV-G (WITH EGR COOLER)].)  [SKYACTIV-G (WITH EGR COOLER)].)	11	• Inspect the fuel pressure sensor. (See FUEL PRESSURE SENSOR INSPECTION [SKYACTIV-G (WITHOUT EGR COOLER)].) (See HIGH FUEL PRESSURE SENSOR INSPECTION	Yes	(See FUEL INJECTOR REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITH CYLINDER
• Is there any malfunction? No Go to Step 13.			No	Go to Step 13.

# NO.20 FUEL ODOR (IN ENGINE COMPARTMENT) [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)]

SM2897131

id0103q580260

FUEL ODOR (IN ENGINE COMPARTMENT)
Gasoline fuel smell or visible leakage.
<ul> <li>Missing or loose fuel filler cap</li> <li>Fuel filler cap malfunction (seal malfunction)</li> <li>Fuel leakage from fuel system</li> <li>Charcoal canister damage</li> <li>Vacuum hose (disconnection, damage) between fuel tank, charcoal canister, purge solenoid valve, and intake manifold</li> <li>Fuel leakage at the fuel injector</li> <li>Purge solenoid valve malfunction (stuck)</li> <li>Warning</li> <li>The following troubleshooting flow chart contains the fuel system diagnosis and repair procedures. Read the following warnings before performing the fuel system services:</li> <li>Fuel vapor is hazardous. It can easily ignite, causing serious injury and damage. Always keep sparks and flames away from fuel.</li> <li>Fuel line spills and leakage are dangerous. Fuel can ignite and cause serious injury or death and damage.</li> <li>Fuel can also irritate skin and eyes. To prevent this, always complete "BEFORE SERVICE PRECAUTION" and "AFTER SERVICE PRECAUTION" described in this manual. (See BEFORE SERVICE PRECAUTION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].) (See AFTER SERVICE PRECAUTION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)</li> <li>Caution</li> <li>Disconnecting/connecting the quick release connector without cleaning it may possibly cause damage to the fuel pipe and quick release connector. Always clean the quick release connector joint area before</li> </ul>
disconnecting/connecting, and make sure that it is free of foreign matter.

## Caution

• Verify the malfunction symptom according to not only the PID value but also the symptom troubleshooting.

# **Related PIDs**

	Item (definition)	Unit/Condition	Definition	Condition/Specification (Reference)
		KPa {MPA}, mBar {BAR}, psi, in H20	Fuel	Displays fuel pressure
i	FUEL_PRES	V	pressure	Idle (ECT 80 °C {176 °F}) • Fuel pressure is 10 MPa {102 kgf/cm <sup>2</sup> , 1450 psi}: Approx. 1.4
L	LOAD	%	Engine load	<ul> <li>Idle (after warm up): Approx. 16.07%</li> <li>Racing (engine speed is 2,000 rpm): Approx. 13.33%</li> <li>Racing (engine speed is 4,000 rpm): Approx. 15.29%</li> </ul>

21 **ENGINE NOISE** 

POSSIBLE CAUSE | Buzzing sound is heard from exhaust pipe during cold engine start:

#### Note

- During a cold engine start, sound occurs for up to approx. 30 s with fast idle up for a drive-by-wire control and the warm-up promotion spark retard correction for ignition timing control.
- Sound occurs from drive-by-wire control, ignition control (vehicle is normal)
- Dvnamic damper loose
- Exhaust system installation condition
- Intake system installation condition

#### Squeal, click, or chirp noise:

- Improper engine oil level
- Loose installation of solenoid valves
- Improper drive belt tension
- Generator installation
- Auto tensioner bearing malfunction
- Splash shield or under cover loose (splash water to drive belt)

#### Thumping/rattling or creaking sound noise:

- Improper drive belt tension
- Loose parts
- Loose fitting heater hoses vibrating the heater hose bracket protector

#### Hissing sound noise:

- Vacuum leakage
- Loose spark plug
- Air leakage from the intake-air system

#### Clattering noise:

Loose parts

#### Pulsing sound is heard:

· Exhaust shutter valve malfunction

# Lightly tapping or rumbling noise:

- Dynamic damper loose
- Exhaust system loose
- Intake-air system loose

#### Other noise:

- Electric variable valve timing actuator malfunction
- Hydraulic variable valve timing actuator malfunction
- Timing chain noise
- Hydraulic lash adjuster (HLA) noise

# Warning

- The following troubleshooting flow chart contains the fuel system diagnosis and repair procedures. Read the following warnings before performing the fuel system services:
  - Fuel vapor is hazardous. It can easily ignite, causing serious injury and damage. Always keep sparks and flames away from fuel.
  - Highly pressurized fuel may spray out if the fuel line is cut. Due to the following dangers occurring with a fuel spray, always complete the "Fuel Line Safety Procedure" to prevent the fuel from spraying. (See BEFORE SERVICE PRECAUTION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)
    - Fuel may cause irritation if it comes in contact with skin and eyes.
    - If fuel ignites and causes a fire, it may lead to serious injury or death, and damage to property and facilities.
  - Fuel is highly flammable and dangerous. Fuel line spills and leakage can cause serious injury or death, and damage to equipment. Always refer to the "Quick Release Connector Removal/Installation (fuel system)" before performing the fuel hose installation, and execute the "Fuel Leakage Inspection" after installation. (See QUICK RELEASE CONNECTOR (FUEL SYSTEM) REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].) (See AFTER SERVICE PRECAUTION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)

#### Caution

STEP	INSPECTION	RESULTS	ACTION
	VERIFY IF THERE IS KNOCK SOUND • Is knocking noise present?	Yes	Perform the symptom troubleshooting "NO.13 KNOCKING/PINGING-ACCELERATION/CRUISE". (See NO.13 KNOCKING/PINGING-ACCELERATION/CRUISE [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)
9		No	If noise comes from engine internal: Inspect the following:  — Timing chain — Hydraulic lash adjuster (HLA) noise — Electric variable valve timing actuator — Hydraulic variable valve timing actuator — Engine compression Repair or replace the malfunctioning part according to the inspection results.
10	Verify the test results.  • If normal, return to the diagnostic index to service any additional symptoms. (See SYMPTOM DIAGNOSTIC INITIALIZED SYMPTOM DIAGN		

later calibration is available. Retest.

— Engine compression (See COMPRESSION INSPECTION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)

# Electric Variable Valve Timing Driver Control System Inspection

1.Connect the M-MDS to the DLC-2.

2.Perform the KOER self test. (See KOEO/KOER SELF TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)

3. Verify that DTC P0010:00 or P1380:00 is not displayed. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)

• If DTC P0010:00 or P1380:00 is displayed, perform the DTC inspection. (See DTC P0010:00 [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) (See DTC P1380:00 [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)

4.Perform the Drive Mode 03 (Variable Valve Timing, A/F Sensor Heater, HO2S Heater, A/F Sensor, HO2S and TWC Repair Verification Drive Mode). (See OBD-II DRIVE MODE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)

5. Verify that DTC P0011:00 or P0012:00 is not displayed. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)

• If DTC P0011:00 or P0012:00 is displayed, perform the DTC inspection. (See DTC P0011:00, P0012:00 [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)

6.Access the following PCM PIDs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)

- VT\_IN\_ACT
- VT\_IN\_DES

#### Caution

- While performing this step, always operate the vehicle in a safe and lawful manner.
- When the M-MDS is used to observe monitor system status while driving, be sure to have another technician with you, or record the data in the M-MDS using the PID/DATA MONITOR AND RECORD capturing function and inspect later.

7.Accelerate and decelerate the vehicle, and drive at normal speed, and verify that the data monitor item VT\_IN\_ACT value changes i conjunction with the VT\_IN\_DES value.

• If this change cannot be verified, replace the electric variable valve timing motor/driver. (See ELECTRIC VARIABLE VALVE TIMING MOTOR/DRIVER REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].)

## Engine Oil Solenoid Valve Control System Inspection

1.Connect the M-MDS to the DLC-2.