

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2005 CHEVROLET Express OEM Service and Repair Workshop Manual

[Go to manual page](#)




YOUR CURRENT VEHICLE

Valve Rocker Arm and Push Rod Replacement

Valve Rocker Arm and Push Rod Replacement

Removal Procedure

1. Remove the valve rocker arm cover.
 - [Valve Rocker Arm Cover Replacement - Left Side](#)
 - [Valve Rocker Arm Cover Replacement - Right Side](#)



1. Lubricate the flange of the valve rocker arm bolts with clean engine oil. [Adhesives, Fluids, Lubricants, and Sealers](#)
2. Lubricate the valve rocker arms and push rods with clean engine oil. [Adhesives, Fluids, Lubricants, and Sealers](#)

3. NOTE

Note


- When using the valve train components again, always install the components to the original location and position.
- Valve lash is net build. No valve adjustment is required.
- Ensure the push rods seat properly to the valve lifter sockets.
- The rocker arm bolts are not serviced separately.
- DO NOT tighten the rocker arm bolts at this time.

Valve Push Rod(1) »Install

YOUR CURRENT VEHICLE

Valve Rocker Arm Cover Insulator Replacement - Left Side

Valve Rocker Arm Cover Insulator Replacement - Left Side (LT1 With Z52)



Valve Rocker Arm Cover Insulator Replacement - Left Side


Callout	Component Name
Preliminary Procedures 1. Intake Manifold Cover Replacement 2. Positive Crankcase Ventilation Hose/Pipe/Tube Replacement.	
1	Valve Rocker Arm Cover Insulator Fasteners



YOUR CURRENT VEHICLE

Valve Rocker Arm Cover Insulator Replacement - Left Side

Valve Rocker Arm Cover Insulator Replacement - Left Side (LT1 Without Z52)



Valve Rocker Arm Cover Insulator Replacement - Left Side

Callout	Component Name
Preliminary Procedures	
1. Oil Level Indicator Tube Replacement	
2. Engine Oil Filler Cap »Remove	
3. Intake Manifold Cover Replacement	

