

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.


2009 MAZDA 3 MPS / MAZDASPEED3 OEM Service and Repair Workshop Manual

[Go to manual page](#)

CONTROL SYSTEM DIAGRAM [SKYACTIV-G 2.5T]

SM2897714

id0140h080030



ac5uuw00011159

CRANKSHAFT POSITION (CKP) SENSOR REMOVAL/INSTALLATION [SKYACTIV-G 2.5T]

SM2897716

id0140h080060

Replacement Part

O-ring
Quantity: 1
Location of use: CKP sensor

Oil and Chemical Type

Engine oil
Type: Recommended oil


Caution

- When replacing the CKP sensor, make sure there is no foreign matter on it such as metal shavings. If it is installed with foreign matter, the sensor output signal will malfunction resulting from fluctuation in magnetic flux and cause a deterioration in engine control.

- 1.Turn the steering wheel to full right lock.
- 2.Disconnect the negative battery terminal. (See [NEGATIVE BATTERY TERMINAL DISCONNECTION/CONNECTION.](#))
- 3.Lift up the vehicle.
- 4.Remove the front splash shield (RH). (See [SPLASH SHIELD REMOVAL/INSTALLATION.](#))
- 5.Remove the service hole cover (installed to front under cover No.2).


Voltage Inspection

1. Remove the MAF sensor/IAT sensor No.1 without disconnect the connector. (See [MASS AIR FLOW \(MAF\) SENSOR/INTAKE AIR TEMPERATURE \(IAT\) SENSOR NO.1 REMOVAL/INSTALLATION \[SKYACTIV-G 2.5T\].](#))
2. Connect the M-MDS to the DLC-2.
3. Switch the ignition ON (engine off).
4. As the air gradually approaches the MAF detection part of the MAF sensor/IAT sensor No.1, verify that the MAF sensor output voltage (PID: MAF) varies. (See [ON-BOARD DIAGNOSTIC TEST \[PCM \(SKYACTIV-G 2.5T\)\].](#))



- If not as specified, replace the MAF sensor/IAT sensor No.1. (See [MASS AIR FLOW \(MAF\) SENSOR/INTAKE AIR TEMPERATURE \(IAT\) SENSOR NO.1 REMOVAL/INSTALLATION \[SKYACTIV-G 2.5T\].](#))

Specification (Reference)



BAROMETRIC PRESSURE (BARO) SENSOR INSPECTION [SKYACTIV-G 2.5T]

SM2897719

id0140h080110

Note

- Because the BARO sensor is integrated in the PCM, replacing the BARO sensor includes replacement of the PCM.

1. Connect the M-MDS to the DLC-2.

2. Switch the ignition ON (engine off).

3. Measure the barometric pressure using a barometer.

4. Verify that the measured barometric pressure and the actually measured barometric pressure (PID: BARO) input from the BARO sensor match. (See [ON-BOARD DIAGNOSTIC TEST \[PCM \(SKYACTIV-G 2.5T\)\]](#).) (See [PCM INSPECTION \[SKYACTIV-G 2.5T\]](#).)

- If the measured barometric pressure and the actually measured barometric pressure do not match, replace the PCM. (See [PCM REMOVAL/INSTALLATION \[SKYACTIV-G 2.5T\]](#).)

control.

1. Disconnect the negative battery terminal. (See [NEGATIVE BATTERY TERMINAL DISCONNECTION/CONNECTION.](#))
2. Remove the plug hole plate. (See [PLUG HOLE PLATE REMOVAL/INSTALLATION \[SKYACTIV-G 2.5T\].](#))
3. Disconnect the exhaust CMP sensor connector.
4. Remove the exhaust CMP sensor. (See [CAMSHAFT POSITION \(CMP\) SENSOR REMOVAL/INSTALLATION \[SKYACTIV-G 2.5T\].](#))
5. Verify that there are no metal shavings on the exhaust CMP sensor.
 - If there is a malfunction, remove any metal shavings that are adhering.


Voltage inspection

Caution

- When replacing the CMP sensor, make sure there is no foreign matter on it such as metal shavings. If it is installed with foreign matter, the sensor output signal will malfunction resulting from fluctuation in magnetic flux and cause a deterioration in engine control.
- If the wiring harnesses or waterproof connectors are damaged, water penetrating the connector will cause a sensor malfunction. To prevent this, be careful not to damage wiring harnesses or waterproof connectors.


1. Idle the engine.
2. Measure the output voltage wave pattern between exhaust CMP sensor terminals A and B using an oscilloscope.

- If not as specified, replace the exhaust CMP sensor. (See [CAMSHAFT POSITION \(CMP\) SENSOR REMOVAL/INSTALLATION \[SKYACTIV-G 2.5T\].](#))



Output voltage (Reference)

Terminal	Voltage (V)	Condition
A	Above 4.8	High output *
	Below 0.8	Low output *



6.Remove the intake CMP sensor.

7.Install in the reverse order of removal.


Exhaust CMP Sensor


1.Disconnect the negative battery terminal. (See [NEGATIVE BATTERY TERMINAL DISCONNECTION/CONNECTION.](#))

2.Remove the plug hole plate. (See [PLUG HOLE PLATE REMOVAL/INSTALLATION \[SKYACTIV-G 2.5T\].](#))

3.Disconnect the exhaust CMP sensor connector.

4.Remove the bolt.





6. Install in the reverse order of removal.

7. Refill the engine coolant. (See [ENGINE COOLANT REPLACEMENT \[SKYACTIV-G 2.5T\]](#).)

INTAKE AIR TEMPERATURE (IAT) SENSOR INSPECTION [SKYACTIV-G 2.5T]

SM2897724

id0140h080220

IAT Sensor No.1

Function inspection

- 1.Connect the M-MDS to the DLC-2.
- 2.Switch the ignition ON (engine off).
- 3.Display the PID IAT. (See [ON-BOARD DIAGNOSTIC TEST \[PCM \(SKYACTIV-G 2.5T\)\]](#).) (See [PCM INSPECTION \[SKYACTIV-G 2.5T\]](#).)
- 4.Compare the voltage and temperature indications for the PID IAT with the standard in the table indicated below.
 - If they do not match the standard, perform the resistance inspection. (See [Resistance inspection](#).)

Standard


IAT	
V	°C {°F}
Approx. 2.70	20 {68}
Approx. 1.80	40 {104}
Approx. 1.20	60 {140}

Resistance inspection

Note

- The MAF sensor and IAT sensor No.1 cannot be removed as a single unit. When replacing the IAT sensor No.1, replace the MAF sensor/IAT sensor No.1.
- 1.Disconnect the negative battery terminal. (See [NEGATIVE BATTERY TERMINAL DISCONNECTION/CONNECTION](#).)
 - 2.Disconnect the MAF sensor/IAT sensor No.1 connector.

IAT (°C {°F})	Resistance (Kilohms)
20 {68}	Approx. 2.5
80 {176}	Approx. 0.323
130 {266}	Approx. 0.0893



ac9uuw00007704