

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.


2012 MAZDA 3 / Axela Hatchback OEM Service and Repair Workshop Manual

[Go to manual page](#)

Step	Inspection	Results	Action
3	INSPECT BACKUP VOLTAGE CIRCUIT FOR SHORT TO GROUND OR OPEN CIRCUIT <ul style="list-style-type: none"> • Reconnect all disconnected connectors. • Access the VPWR PID using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITHOUT CYLINDER DEACTIVATION))].) (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) • Verify the VPWR PID value. • Is the VPWR PID value B+? 	Yes	Go to the next step.

•If there is any vehicle malfunction complaint lodged by a customer, perform malfunction diagnosis according to the troubleshooting procedure.

Troubleshooting Procedure



DTC U0405:00 [DSC HU/CM]

SM2898116

id04026289340

DTC	U0405:00	Abnormal message from PCM
DETECTION CONDITION	• Correct data cannot be received from PCM	
FAIL-SAFE FUNCTION	Refer to “DTC Table” and “Fail-safe Function Malfunction Contents”. (See DTC TABLE [DSC HU/CM].)	
POSSIBLE CAUSE	• PCM malfunction	
SYSTEM WIRING DIAGRAM	Not applicable	

Diagnostic procedure

Step	Inspection	Results	Action
1	INSPECT FOR PCM MALFUNCTION <ul style="list-style-type: none">• Switch the ignition to off.• Using the M-MDS, perform the DTC inspection for the PCM. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITHOUT CYLINDER DEACTIVATION))].) (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-D 2.2)].) (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5T)].)• Are any DTCs detected?	Yes	Go to applicable DTC inspection. (See DTC TABLE [PCM (SKYACTIV-G 2.5 (WITHOUT CYLINDER DEACTIVATION))].) (See DTC TABLE [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].) (See DTC TABLE [PCM (SKYACTIV-D 2.2)].) (See DTC TABLE [PCM (SKYACTIV-G 2.5T)].)
		No	Go to the next step.
2	VERIFY THAT THE SAME DTC IS NOT PRESENT <ul style="list-style-type: none">• Using the M-MDS, clear the DTC from the DSC HU/CM. (See CLEARING DTC [DSC HU/CM].)• Using the M-MDS, perform the DSC HU/CM DTC inspection. (See DTC INSPECTION [DSC HU/CM].)• Are the same DTCs present?	Yes	Repeat the inspection from Step 1. If the malfunction recurs, replace the PCM, then go to the next step. (See PCM REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITHOUT CYLINDER DEACTIVATION)].) (See PCM REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].) (See PCM REMOVAL/INSTALLATION [SKYACTIV-D 2.2)].) (See PCM REMOVAL/INSTALLATION [SKYACTIV-G 2.5T)].)
		No	Go to the next step.

Step	Inspection	Results	Action
3	VERIFY THAT NO OTHER DTCS ARE PRESENT • Are any other DTCs output?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [DSC HU/CM] .)
		No	DTC troubleshooting completed.



Sample

Step	Inspection	Results	Action
4	VERIFY THAT THE SAME DTC IS NOT PRESENT <ul style="list-style-type: none"> Using the M-MDS, clear the DTC from the DSC HU/CM. (See CLEARING DTC [DSC HU/CM].) Using the M-MDS, perform the DSC HU/CM DTC inspection. (See DTC INSPECTION [DSC HU/CM].) Are the same DTCs present? 	Yes	Repeat the inspection from Step 1. If the malfunction recurs, replace the DSC HU/CM, then go to the next step. (See DSC HU/CM REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITHOUT CYLINDER DEACTIVATION)].) (See DSC HU/CM REMOVAL/INSTALLATION [SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION)].) (See DSC HU/CM REMOVAL/INSTALLATION [SKYACTIV-D 2.2].) (See DSC HU/CM REMOVAL/INSTALLATION [SKYACTIV-G 2.5T].)
		No	Go to the next step.
5	VERIFY THAT NO OTHER DTCS ARE PRESENT <ul style="list-style-type: none"> Are any other DTCs output? 	Yes	Go to the applicable DTC inspection. (See DTC TABLE [DSC HU/CM].)
		No	DTC troubleshooting completed.

DTC U3003:08/U3003:16/U3003:17 [DSC HU/CM]

SM2898120

id04026290200

DTC	U3003:08, U3003:16, U3003:17	Power supply system
DETECTION CONDITION	<ul style="list-style-type: none">• U3003:08<ul style="list-style-type: none">— While the vehicle is traveling at a speed of 10km/h {6.2 mph} or more, a CAN signal error caused by low power supply voltage is detected.• U3003:16<ul style="list-style-type: none">— Low ignition voltage (7.9–9.6 V) is detected at the voltage monitor of the solenoid valve or motor monitor. (Except engine cranking condition)— Low ignition voltage (6.0–7.9 V) is detected at the voltage monitor of the solenoid valve or motor monitor.— Low ignition voltage (below 6.0 V) is detected at the voltage monitor of the solenoid valve or motor monitor.• U3003:17<ul style="list-style-type: none">— High ignition voltage (17 V or more) is detected at the voltage monitor of the solenoid valve or motor monitor.	
FAIL-SAFE FUNCTION	Refer to “DTC Table” and “Fail-safe Function Malfunction Contents”. (See DTC TABLE [DSC HU/CM].)	
POSSIBLE CAUSE	<ul style="list-style-type: none">• Battery deterioration• Generator malfunction• Fuse (SRS1 7.5A, ABS/DSC S 30A, ABS/DSC M 50A) malfunction• Open or short circuit in wiring harness between DSC HU/CM terminal A and battery• Open or short circuit in wiring harness between DSC HU/CM terminal B and battery• Open or short circuit in wiring harness between DSC HU/CM terminal Q and battery• Open circuit in wiring harness between DSC HU/CM terminal AL and body ground• Poor connection at connectors (female terminal)	
<div><div><div><div><div>BATTERY</div><div></div></div><div><div>DSC HU/CM WIRING HARNESS-SIDE CONNECTOR</div><div></div></div></div></div></div>		

DTC U0420:00 [DSC HU/CM]

SM2898121

id04026290500

DTC	U0420:00	Abnormal message from EPS control module
DETECTION CONDITION	•Correct data cannot be received from EPS control module	
FAIL-SAFE FUNCTION	Refer to “DTC Table” and “Fail-safe Function Malfunction Contents”. (See DTC TABLE [DSC HU/CM].)	
POSSIBLE CAUSE	•EPS control module malfunction	
SYSTEM WIRING DIAGRAM	Not applicable	

Diagnostic procedure

Step	Inspection	Results	Action
1	INSPECT FOR EPS CONTROL MODULE MALFUNCTION •Switch the ignition to off. •Using the M-MDS, perform the DTC inspection for the EPS control module. (See DTC INSPECTION [ELECTRIC POWER STEERING (EPS) CONTROL MODULE].) •Are any DTCs detected?	Yes	Go to applicable DTC inspection. (See DTC TABLE [ELECTRIC POWER STEERING (EPS) CONTROL MODULE].)
		No	Go to the next step.
2	VERIFY THAT THE SAME DTC IS NOT PRESENT •Using the M-MDS, clear the DTC from the DSC HU/CM. (See CLEARING DTC [DSC HU/CM].) •Using the M-MDS, perform the DSC HU/CM DTC inspection. (See DTC INSPECTION [DSC HU/CM].) •Are the same DTCs present?	Yes	Repeat the inspection from Step 1. If the malfunction recurs, replace the EPS control module, then go to the next step. (See STEERING WHEEL AND COLUMN REMOVAL/INSTALLATION.)
		No	Go to the next step.
3	VERIFY THAT NO OTHER DTCS ARE PRESENT •Are any other DTCs output?	Yes	Go to the applicable DTC inspection. (See DTC TABLE [DSC HU/CM].)
		No	DTC troubleshooting completed.

DTC
C0030:07/C0031:07/C0031:29/C0031:2F/C0031:64/C0033:07/C0034:07/C0034:29/C0034:2F/C0034:64/C0036:07/C0037:07/C0037:29/C0037:2F/C0037:64/C0039:07/C003A:07/C003A:29/C003A:2F/C003A:64 [DSC HU/CM]

SM2898124

id04026290610

Note

- When only the driving wheels are rotated while the vehicle is jacked up, DTCs C0037:29 and C003A:29 are input to the memory.

DTC	C0030:07	LF ABS sensor rotor
	C0031:07, C0031:29, C0031:2F, C0031:64	LF ABS wheel-speed sensor/ABS sensor rotor
	C0033:07	RF ABS sensor rotor
	C0034:07, C0034:29, C0034:2F, C0034:64	RF ABS wheel-speed sensor/ABS sensor rotor
	C0036:07	LR ABS sensor rotor
	C0037:07, C0037:29, C0037:2F, C0037:64	LR ABS wheel-speed sensor/ABS sensor rotor
	C0039:07	RR ABS sensor rotor
	C003A:07, C003A:29, C003A:2F, C003A:64	RR ABS wheel-speed sensor/ABS sensor rotor
DETECTION CONDITION		<ul style="list-style-type: none">• C0030:07, C0033:07, C0036:07, C0039:07<ul style="list-style-type: none">— Periodic abnormality is detected in the signal wave pattern from the ABS wheel-speed sensors.• C0031:07, C0034:07, C0037:07, C003A:07<ul style="list-style-type: none">— While the vehicle is traveling at a speed of 10 km/h {6.2 mph} or more, no signal in any of the four wheels or an extremely low vehicle speed signal is detected.• C0031:29, C0034:29, C0037:29, C003A:29<ul style="list-style-type: none">— The wheel-speed signal is not input or an extremely low wheel-speed signal is detected from any of the four wheels when driving at a vehicle speed of 10 km/h {6.2 mph} or more• C0031:2F, C0034:2F, C0037:2F, C003A:2F<ul style="list-style-type: none">— The wheel speed or acceleration speed in any of the 4 wheels is not within the specification.— ABS control continues to operate for 28 s or more.• C0031:64, C0034:64, C0037:64, C003A:64<ul style="list-style-type: none">— While the vehicle is traveling at a speed of 20 km/h {12 mph} or more, an extremely high vehicle speed signal in any of the four wheels is detected.
FAIL-SAFE FUNCTION		Refer to “DTC Table” and “Fail-safe Function Malfunction Contents”. (See DTC TABLE [DSC HU/CM].)
POSSIBLE CAUSE		<ul style="list-style-type: none">• ABS sensor rotor malfunction (missing ABS sensor rotor teeth due to foreign material obstruction)• ABS wheel-speed sensor or ABS sensor rotor installation malfunction (If the ABS sensor rotor is installed at an angle, it may cause output of abnormal wave pattern at high speeds.)• Excessive clearance between the ABS wheel-speed sensor and sensor rotor• ABS wheel-speed sensor malfunction• DSC HU/CM malfunction• Continuous ABS operation

DTC C0051:62/C0051:64/C0051:67/C0051:85 [DSC HU/CM]

SM2898125

id04026290620

DTC	C0051:62, C0051:64, C0051:67, C0051:85	Steering angle sensor
DETECTION CONDITION	<p>•C0051:62</p> <p>—The difference between the steering angle calculated by each sensor and the steering angle from the steering angle sensor is the specification or more when the vehicle is driven in a straight line.</p> <p>•C0051:64</p> <p>—The difference between the steering angle calculated by each sensor and the steering angle from the steering angle sensor exceeds the specification.</p> <p>•C0051:67</p> <p>—The neutral position of the steering angle cannot be estimated from the signals from the ABS wheel-speed sensors and the SAS control module.</p> <p>Note</p> <p>•Each time the ignition is switched ON, the DSC HU/CM calculates the steering angle neutral position based on the signals from each sensor and each module.</p> <p>•If the vehicle is driven as follows just after the engine is started, DTC C0051:67 may be output.</p> <ul style="list-style-type: none"> —Vehicle is accelerated rapidly while being steered right or left —Vehicle is driven on abnormal road surface such as banked road —Vehicle is driven on continuously curved road such as mountain road <p>•If the DTC is a past malfunction during DTC inspection, it does not indicate a vehicle malfunction.</p> <p>•C0051:85</p> <p>—The steering angle sensor detects signal modulation or steering angle that exceeds specification.</p>	
FAIL-SAFE FUNCTION	Refer to “DTC Table” and “Fail-safe Function Malfunction Contents”. (See DTC TABLE [DSC HU/CM] .)	
POSSIBLE CAUSE	<p>•C0051:62, C0051:64, C0051:67, C0051:85</p> <ul style="list-style-type: none"> —Improper installation or positioning of the steering angle sensor —Steering angle sensor malfunction —DSC HU/CM malfunction —Connector or terminal malfunction <p>•C0051:67</p> <ul style="list-style-type: none"> —Vehicle is accelerated rapidly while being steered right or left —Vehicle is driven on abnormal road surface such as banked road —Vehicle is driven on continuously curved road such as mountain road 	
SYSTEM WIRING DIAGRAM	Not applicable	

Diagnostic procedure