

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2013 MAZDA 3 MPS / MAZDASPEED3 OEM Service and Repair Workshop Manual

Go to manual page

NO KICKDOWN [FW6A-EL, FW6AX-EL]


SM2898379

id05031710160

TROUBLESHOOTING ITEM	No kickdown
DESCRIPTION	• Does not downshift when accelerator pedal is fully depressed within kickdown range.
POSSIBLE CAUSE	Signal malfunction — APP sensor malfunction

Step	Inspection	Results	Action
1	INSPECT SIGNAL PARTS FOR MALFUNCTION Inspect the value at the following PCM PID using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITHOUT CYLINDER DEACTIVATION))].) (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5 (WITH CYLINDER DEACTIVATION))].)	Yes	Repair or replace any malfunctioning parts according to the inspection result.
	— APP (APP sensor)Is there any malfunction?	No	Symptom troubleshooting is completed.






*1:(See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [TYPE-A (SKYACTIV-G 2.5T, SKYACTIV-D 2.2)].) (See CONTROLLER AREA NETWORK (CAN) MALFUNCTION DIAGNOSIS FLOW [TYPE-B].)

Repair Order Form


—Shake the wiring harness or connector of the electrical component which is suspected to be the cause of the malfunction, and inspect for occurrence of any malfunction or DTCs.



—Inspect the female terminals on the connector of the electric component which is suspected to be the cause of the malfunction for poor connection. (See ELECTRICAL SYSTEM)

Note





QUICK DIAGNOSIS CHART [GW6A-EL, GW6AX-EL]

SM2898397

id05032010040

					_																ν.	A DE		_
	_	_	_		_		_				_				1						X: /	APF	'LII	=1
EHICLE DOES NOT MOVE IN D, M OR R POSITION	\perp	L					╙							Х	X	Х				_		Ш	_	_
EHICLE MOVES IN P POSITION, OR ARKING GEAR DOES NOT DISENGAGE WHEN P IS DISENGAGED															x									
XCESSIVE CREEP	\top			Х																		П		Τ
IO CREEP AT ALL	+	\vdash	\vdash	Х			\vdash								\vdash	\vdash				\vdash		H		
OW MAXIMUM SPEED AND POOR ACCELERATION	+	х	х		х		\vdash				х				\vdash	\vdash					\vdash	H		_
IO SHIFTING	+	-	Х		-			х	Х	Х		х			$^{+}$							\Box		_
OES NOT SHIFT TO 5GR OR 6GR	+	-	X				\vdash			Х					\vdash						\vdash	H		
BNORMAL SHIFTING	×	X	-					_	_	Х	_	х			+							\vdash		
REQUENT SHIFTING	+^	Ĥ	^				\vdash	^	Ĥ	-	X				\vdash							\square		
HIFT POINT IS HIGH OR LOW	×	\vdash	\vdash				\vdash	Y	x	X		x			+	\vdash	\vdash						-	
IO KICKDOWN	+^	\vdash					\vdash	^	^	^	x	^	_									Н	Н	
NGINE FLARES UP OR SLIPS WHEN	+	\vdash					\vdash		H				H		\vdash								Н	_
IPSHIFTING OR DOWNSHIFTING UDDER UPON TORQUE CONVERTER	_	-	Х				L				Х													>
LUTCH (TCC) OPERATION		Х					L				Х			Х										
XCESSIVE SHIFT SHOCK FROM N TO D OR I TO R POSITION		х		Х	х						Х								Х)
LOW ENGAGING AFTER OPERATING ELECTOR LEVER FROM N TO D POSITION																	х					Х		L
XCESSIVE SHIFT SHOCK IS FELT WHEN PSHIFTING AND DOWNSHIFTING					х						х								Х)
XCESSIVE SHIFT SHOCK ON ORQUE CONVERTER CLUTCH (TCC)		х			х						х			х)
IOISE OCCURS AT IDLE	+	\vdash						7					abla							\vdash		Н		Ī
VHEN VEHICLE IS STOPPED N ALL POSITIONS					X						k		Х	Х										
IOISE OCCURS AT IDLE VHEN VEHICLE IS STOPPED					х						2			Х										
D, M OR R POSITION									K															
RANSAXLE OVERHEATS	Х	X									Х	Χ			П					х	Х	Х		Г
NGINE STALLS WHEN SHIFTED TO , M OR R POSITION				х										Х									х	
TARTER DOES NOT WORK					Х	Х																		Τ
EAR POSITION INDICATION DOES NOT LUMINATE IN M POSITION		T					х													х				
EAR POSITION INDICATION ILLUMINATES N.P. R., N. AND D. POSITIONS							х								Γ									
MANUAL SHIFT MODE INDICATION DOES NOT LUMINATE IN M POSITION/MANUAL SHIFT MODE INDICATION ILLUMINATES IN D OSITION							х																	
TF SEEPING FROM AUTOMATIC TRANSAXLE	\top	Т															Х	Х				П		Τ
ITEM /	1			z	z										Z		_					z		_
/				ATIC	은	<u>5</u>	<u>S</u>			S					은		IAG		느			읦		
SYMPTOM				FIC	S	Ē	S	z		Ξ		z			2		Š	ш	Z Z z			š		c
STWPTOW	<u>N</u>	NO NO	Ñ.	SPEC	MALF	PER.	ALFU	OILO	N	LFU.	Ñ.	CTIC	_	NO	ALFL		AND	O NO	NO SIOIS		<u>S</u>	AALF	8	MILE
	NC.	S	ONC.	ED 8	STEM	NC TO N	EBM	Ŋ.	NCT	R MA	NC.	FUN)TIO	ER NCTJ	M MS	ž	NOIT	T ATI	N OR		NCT	Š	2	i
	ECT SENSOR MALFUNCTION	CKP SENSOR MALFUNCTION	MAF SENSOR MALFUNCTION	NOT WITHIN IDLE SPEED SPECIFICATION	ENGINE CONTROL SYSTEM MALFUNCTION	IMMOBILIZER SYSTEM OPERATING OR SYSTEM MALFUNCTION	INSTRUMENT CLUSTER MALFUNCTION	BARO SENSOR MALFUNCTION	IAT SENSOR MALFUNCTION	LOW-G (XY) SENSOR MALFUNCTION	APP SENSOR MALFUNCTION	BRAKE SWITCH MALFUNCTION	OIL PUMP MALFUNCTION	TORQUE CONVERTER OPERATING MALFUNCTION	PARKING MECHANISM MALFUNCTION	MANUAL SHAFT STUCK	SEALING DETERIORATION AND DAMAGE	INCORRECT INSTALLATION OF ATX EXTERNAL PART	POOR INSTALLATION OR WORN OF ENGINE MOUNT, SUSPENSION	ATF MALFUNCTION	OIL COOLER MALFUNCTION	CONTROL VALVE BODY MALFUNCTION	TCC PISTON MALFUNCTION	CINIDAD LEGISLENIT TOWN DAILNING
	B	RN	Ä	딥	8	S. ₹	ū	8	Ž	SE	2	힏	AL	Ž₹	Ö	ΑF	H	≅⋠	32	ō	Ž	AL.	ŝ	į
CAUSE OF TROUBLE	S	S	S	Z.	S		Z	SS	O.B.	3	S	₹	2	႘ၒၟ	Ξ	S	님	S É	ST	جَا	曲	>	бl	Ĺ
/ Choose of Indobee	Ä	K	Ä	Ē	Ω̈́	ST	2	S	SS	Č.	H	S	Σ	삥투	NG	A	9	뼕岸	Ξū	ALF	ğ	8	2	Į.
	S	S	FS	×	ZZ.	© ₹	E	잁	S	W-C	S	ΑK	ď	200	关	\exists	Ē	ĞΘ	등	Σ	ŏ	눌	5	블
/	C	Y	¥	Ó	ĭ	€ Œ	100	A	\vdash	5	0	CC.	=	0 0	17	×	Ιŵ	일은	ΙΟŽ	ΙĖ	ı	Q	ŭ	ū

ac5uuw00011436

VEHICLE MOVES IN P POSITION, OR PARKING GEAR DOES NOT DISENGAGE WHEN P IS DISENGAGED [GW6A-EL, GW6AX-EL]

SM2898399

id05032010060

TROUBLESHOOTING ITEM	Vehicle moves in P position, or parking gear does not disengage when P is disengaged
DESCRIPTION	 Vehicle rolls when on a downward slope in P position. Vehicle does not move in D, M and R position when accelerator pedal is depressed, and engine remains in stalled condition.
POSSIBLE CAUSE	1. Parking mechanism malfunction

Step	Inspection	Results	Action
		Yes	Symptom troubleshooting is completed.
1	INSPECT PARKING MECHANISM FOR MALFUNCTION • When the vehicle is stopped on a flat, level road and the engine is off, does the vehicle move when pushed? (In D, N or R position with the brake pedal released.)	No	Replace the parking mechanism. (See AUTOMATIC TRANSAXLE REMOVAL/INSTALLATION [GW6A-EL (SKYACTIV-G 2.5T)].) (See AUTOMATIC TRANSAXLE REMOVAL/INSTALLATION [GW6A-EL (SKYACTIV-D 2.2)].) (See AUTOMATIC TRANSAXLE REMOVAL/INSTALLATION [GW6AX-EL (SKYACTIV-G 2.5T)].) (See AUTOMATIC TRANSAXLE REMOVAL/INSTALLATION [GW6AX-EL (SKYACTIV-D 2.2)].)

LOW MAXIMUM SPEED AND POOR ACCELERATION [GW6A-EL, GW6AX-EL]

SM2898402

id05032010090

TROUBLESHOOTING ITEM	Low maximum speed and poor acceleration
DESCRIPTION	Vehicle acceleration is poor at start.Delayed acceleration when accelerator pedal is depressed while driving.
POSSIBLE CAUSE	 Engine control system malfunction Signal malfunction APP sensor malfunction CKP sensor malfunction MAF sensor malfunction

Step	Inspection	Results	Action
1	INSPECT ENGINE CONTROL SYSTEM FOR MALFUNCTION • Perform the symptom troubleshooting "LACK/LOSS OF POWER-ACCELERATION/CRUISE". (See NO.17 LACK/LOS POWER-ACCELERATION/CRUISE [SKYACTIV-D 2.2].) (See NO.12 LACK/LOSS OF POWER-ACCELERATION/CRUISE [SKYACTIV-G 2.5T].)		Repair or replace any malfunctioning parts according to the inspection result.
	• Is there any malfunction?	No	Go to the next step.
2	INSPECT SIGNAL PARTS FOR MALFUNCTION • Inspect the value at the following PCM PIDs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-D 2.2)].) (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5T)].)	2)].) Yes	Repair or replace any malfunctioning parts according to the inspection result.
2	— APP (APP sensor)— MAF (MAF sensor)— RPM (CKP sensor)• Is there any malfunction?	No	Explain to the customer that the vehicle is not malfunctioning and they should keep an eye on it.

DOES NOT SHIFT TO 5GR OR 6GR [GW6A-EL, GW6AX-EL]

SM2898404

id05032010110

TROUBLESHOOTING ITEM	Does not shift to 5GR or 6GR
DESCRIPTION	 Vehicle does not upshift from 4GR to 5GR or 5GR to 6GR even though vehicle speed is increased. At a vehicle speed range where the transaxle should shift up to 5GR and 6GR gears in D position based on the shift pattern, the transaxle does not shift to 5GR and 6GR gears by gradually releasing the accelerator pedal.
POSSIBLE CAUSE	 Signal malfunction APP sensor malfunction BARO sensor malfunction CKP sensor malfunction ECT sensor malfunction IAT sensor No.1 malfunction MAF sensor malfunction Low-G (XY) sensor (built into SAS control module) malfunction Note When driving on high-altitude roads, the TCM determines that the driving mode is the AAS mode, and may change to a different shift timing from the normal timing. When SPORT mode is selected, a gear lower than NORMAL mode is selected, and the gear is maintained for a longer period of time. (SKYACTIV-G 2.5T) If the engine coolant temperature is low, a gear lower than when in normal mode is selected.

Step	Inspection	Results	Action
1	INSPECT SIGNAL PARTS FOR MALFUNCTION Inspect the value at the following PCM PIDs using the M-MDS. (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-D 2.2)].) (See ON-BOARD DIAGNOSTIC TEST [PCM (SKYACTIV-G 2.5T)].) — APP (APP sensor) — BARO (BARO sensor) — ECT (ECT sensor)	Yes	Repair or replace any malfunctioning parts according to the inspection result.
	 — IAT (IAT sensor No.1) — MAF (MAF sensor) — RPM (CKP sensor) • Is there any malfunction? 	No	Go to the next step.

Step	Inspection	Results	Action
2	VERIFY IF MALFUNCTION CAUSE IS LOW-G (XY) SENSOR • Is there any malfunction?	Yes	Replace the SAS control module. (See SAS CONTROL MODULE REMOVAL/INSTALLATION [TWO-STEP DEPLOYMENT CONTROL SYSTEM - US/CANADA/ISRAEL SPEC.].) (See SAS CONTROL MODULE REMOVAL/INSTALLATION [STANDARD DEPLOYMENT CONTROL SYSTEM - MEXICO SPEC.].)
		No	Symptom troubleshooting is completed.



