

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2014 FORD Focus ST 5 Doors OEM Service and Repair Workshop Manual

Go to manual page

Are the resistances greater than 10,000 ohms?

Yes	GO to N9	
Νο	REPAIR the circuit in question	

N9 CHECK THE VIDEO SIGNAL CIRCUITS BETWEEN THE CHMSL CAMERA AND IPMA (IMAGE PROCESSING MODULE A) FOR A SHORT TO THE VIDEO SHIELD

• Measure:

C9125-3 Ω C9125-5 C9125-4 Ω C9125-5 Are the resistances greater than 10,000 ohms? Yes GO to N10		Positive Lead	Measurement / Action	Negative Lead
C9125-4ΩC9125-5Are the resistances greater than 10,000 ohms?YesGO to N10		C9125-3	Ω	C9125-5
Are the resistances greater than 10,000 ohms? Yes GO to N10		C9125-4	Ω	C9125-5
Yes GO to N10	re 1	he resistances:	greater than 10,000 oh	nms?
	Yes	GO to N10		

N10 CHECK VIDEO SIGNAL CIRCUITS BETWEEN THE CHMSL CAMERA AND IPMA (IMAGE PROCESSING MODULE A) FOR AN OPEN

• Measure:

Positive Lead Measurement / Action Negative Lead

	Positive Lead	Measurement / Action	Negative Lead	
	C9125-2	Ω	C242B-1	
ls res	sistance less th	an 3 ohms ?		
Yes	GO to N13			
No	REPAIR the	circuit.		
N13 (CHECK THE LIN	(LOCAL INTERCONNEC	T NETWORK) CIR	CUIT FOR A SHORT TO GROUND
•	Measure:			
	Positive Lead	Measurement / Action	Negative Lead	
	C9125-2	Ω	Ground	
ls res	sistance greate	r than 10,000 ohms?		
Yes	GO to N14			
No	REPAIR the	circuit.		
N14 (CHECK FOR CO	RRECT CHMSL CAMERA	OPERATION	
•	lgnition OFF. Disconnect and Repair:	inspect the CHMSL came	era connector.	

- corrosion (install new connector or terminals clean module pins)
- damaged or bent pins install new terminals/pins

The system is operating correctly at this time. The concern may have been caused by a loose or corroded connector. ADDRESS the root cause of any connector or pin issues.

PINPOINT TEST O : THE TRAILER CAMERA IS INOPERATIVE

NOTE

No

Before disconnecting the camera or trailer electrical connections, verify that the connectors are properly seated and latched.

Refer to Wiring Diagrams Cell 145for schematic and connector information.

Normal Operation and Fault Conditions REFER to: Parking Aid - System Operation and Component Description

(413-13B Parking Aid - Vehicles With: Parking Aid Camera, Description and Operation).

DTC Fault Trigger Conditions

DTC (diagnostic trouble code)	Description	Fault Trigger Condition
IPMA (image processing module A) B152F:12	Base Camera: Circuit Short To Battery	A continuous and on-demand DTC (diagnostic trouble code) that sets in the IPMA (image processing module A) when there is a circuit shorted to battery on the trailer camera wiring.

Possible Sources

- Fuse
- Wiring, terminals or connectors
- Communication network concern
- Camera
- TR (transmission range) input concern
- IPMA (image processing module A)

Visual Inspection and Pre-checks

- BJB (battery junction box) fuse 25 (10A).
- Verify the tailgate is fully closed.
- Verify the trailer electrical connection is properly seated and latched.

O1 CHECK AND CLEAN THE CAMERA LENS

O4 CHECK FOR DIAGNOSTIC TROUBLE CODES (DTCS) FROM THE IPMA (IMAGE PROCESSING MODULE A) SELF-TEST

• Using the diagnostic scan tool, perform the IPMA (image processing module A) self-test.

Are any Diagnostic Trouble Codes (DTCs) retrieved?

Vos	REFER to th	e IPMA (image processing module A) DTC (diagnostic trouble code) Chart in this
163	section.	
N	C0 to .05	
NO	GO to OS	
05 C	HECK FOR VOL	FAGE AT THE TRAILER CAMERA
•	Ignition OFF.	
•	Disconnect Trai	er tow connector C439 .
•	Measure:	
	Positive Lead	Measurement / Action Negative Lead
	C439-1	Ground
ls th	e voltage great	er than 11 volts?
Yes	GO to O6	
No	INSPECT BJ the fuse is	B (battery junction box) fuse 25 (10A). If the fuse is OK, repair the circuit for an open. If not OK, REFER to the Wiring Diagrams manual to identify the possible causes of the
	short circui	t.
06 C	HECK FOR GRO	UND AT THE TRAILER CAMERA
•	Measure:	

• Measure:

Positive Lead	Measurement / Action	Negative Lead
C439-9	$\overline{\mathbf{v}}$	Ground
C439-10	$\overline{\mathbf{v}}$	Ground

Is any voltage present?

Yes	REPAIR the circuit in question.	
Νο	GO to O9	

O9 CHECK THE VIDEO SIGNAL CIRCUITS BETWEEN THE TRAILER CAMERA AND IPMA (IMAGE PROCESSING MODULE A) FOR A SHORT TO GROUND

- Ignition OFF.
- Measure:

Positive Lead	Measurement / Action	Negative Lead
C439-9	Ω	Ground
C439-10	Ω	Ground

Are the resistances greater than 10,000 ohms?

Yes GO to O10

ſes	GO to O12
No	REPAIR the circuit in question.
12 Cł	ECK THE TRAILER HARNESS PARKING AID CAMERA HARNESS
• In	 spect the trailer harness between C439 and the trailer parking aid camera for: open or short circuits damaged or pushed out pins corrosion
the (es	GO to 013
No	REPAIR the harness.
13 Cł	ECK FOR CORRECT TRAILER CAMERA OPERATION
 Ig Di Re 	nition OFF. sconnect and inspect the trailer camera connector. pair:
	 corrosion (install new connector or terminals – clean module pins)
	 damaged or bent pins – install new terminals/pins
	 pushed-out pins – install new pins as necessary
• Re	connect the trailer camera connector. Make sure it seats and latches correctly.
• 0 the	erate the system and determine if the concern is still present. concern still present?
Yes	TSB (Technical Service Bulletin) , GSB (General Service Bulletin) , SSM (special service message) o

FSA (Field Service Action) . If a service article exists for this concern, DISCONTINUE this test and

Normal Operation and Fault Conditions REFER to: Parking Aid - System Operation and Component Description

(413-13B Parking Aid - Vehicles With: Parking Aid Camera, Description and Operation).

DTC Fault Trigger Conditions

DTC (diagnostic trouble code)	Description	Fault Trigger Condition
IPMA (image processing module A) B14A5:11	Multi-Camera View Switch: Circuit Short To Ground	A continuous and on-demand DTC (diagnostic trouble code) that sets in the IPMA (image processing module A) when the camera selection switch is stuck closed or the circuit is shorted to ground.

Possible Sources

- Wiring, terminals or connectors
- TR (transmission range) input concern
- Vehicle speed input concern
- Camera selection switch
- IPMA (image processing module A)

Visual Inspection and Pre-checks

• Inspect the camera selection switch to verify that the switch is not damaged or stuck in the pressed position.

P1 VERIFY THE CUSTOMER CONCERN

- Ignition ON.
- Verify the operation of the camera selection switch.

Does the camera selection switch operate correctly?

YesCLEAR the DTC (diagnostic trouble code) . The system is operating correctly at this time. The
concern may have been caused by high network traffic or the driver's perception of how the
parking aid system operates. REFER to the Owner's Manual.NoGO to P2

P2 CHECK FOR DIAGNOSTIC TROUBLE CODES (DTCS) FROM THE IPMA (IMAGE PROCESSING MODULE A) SELF-TEST

P5 CHECK FOR GROUND AT THE CAMERA SELECTION SWITCH

- Ignition OFF.
- Disconnect Instrument panel center stack left switch C2480 .
- Measure:

Positive Lead	Measurement / Action	Negative Lead
C2480-3	Ω	Ground

Is the resistance less than 3 ohms?

Yes	GO to P6
No	REPAIR the circuit.

P6 CHECK THE CAMERA SELECTION SWITCH CIRCUIT FOR AN OPEN

- Disconnect IPMA (image processing module A) C242B .
- Measure:

Positive Lead	Measurement / Action	Negative Lead
C242B-10	Ω	C2480-2

Is the resistance less than 3 ohms?

Yes	INSTALL a new instrument panel console switch assembly. If the concern is still present after replacing the switch, GO to P9	
Νο	REPAIR the circuit.	

- Repair:
 - corrosion (install new connector or terminals clean module pins)
 - damaged or bent pins install new terminals/pins
 - pushed-out pins install new pins as necessary
- Reconnect the IPMA (image processing module A) connectors. Make sure they seat and latch correctly.
- Operate the system and determine if the concern is still present.

Is the concern still present?

	CHECK OASIS (Online Automotive Service Information System) for any applicable service articles:			
	TSB (Technical Service Bulletin) , GSB (General Service Bulletin) , SSM (special service message) or			
	FSA (Field Service Action) . If a service article exists for this concern, DISCONTINUE this test and			
Yes	FOLLOW the service article instructions. If no service articles address this concern, INSTALL a new			
	IPMA (image processing module A) .			
	REFER to: Image Processing Module A (IPMA)			
	(419-07 Lane Keeping System, Removal and Installation).			
Nia	The system is operating correctly at this time. The concern may have been caused by a loose or			
NO	corroded connector. ADDRESS the root cause of any connector or pin issues.			

PINPOINT TEST Q : THE VISUAL PARK AID ALERT IS INOPERATIVE - VEHICLES WITH IPMA (IMAGE PROCESSING MODULE A)

Normal Operation and Fault Conditions

REFER to: Parking Aid - System Operation and Component Description(413-13B Parking Aid - Vehicles With: Parking Aid Camera, Description and Operation).

Possible Sources

- Communication network concern
- APIM (SYNC module)
- IPMA (image processing module A)

Q1 VERIFY THE VISUAL PARK AID ALERT IS ENABLED

- Ignition ON.
- Verify that the visual park aid alert is enabled in the infotainment system settings menu. Refer to the Owner's Literature.

Is the visual park aid alert enabled?