

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2018 Ford Edge Service and Repair Manual

Go to manual page

- Mechanical concern
- Suspect sensor concern

Pinpoint Test Steps available in the on-line Workshop Manual.

Copyright © Ford Motor Company



PCM (powertrain control module)	P0013:00	B Camshaft Position Actuator A Control Circuit/Open Bank 1: No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0014:00	B Camshaft Position Timing - Over-Advanced (Bank 1): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0015:00	B Camshaft Position Timing - Over-Retarded (Bank 1): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0016:00	Crankshaft Position - Camshaft Position Correlation (Bank 1 Sensor A): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0017:00	Crankshaft Position - Camshaft Position Correlation (Bank 1 Sensor B): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0018:00	Crankshaft Position - Camshaft Position Correlation (Bank 2 Sensor A): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0019:00	Crankshaft Position - Camshaft Position Correlation (Bank 2 Sensor B): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0020:00	A Camshaft Position Actuator A Control Circuit/Open Bank 2: No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0021:00	A Camshaft Position Timing - Over-Advanced (Bank 2): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0022:00	A Camshaft Position Timing - Over-Retarded (Bank 2): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P0023:00	B Camshaft Position Actuator A Control Circuit/Open Bank 2: No Sub Type Information	GO to Pinpoint Test HK

PCM (powertrain control module)	P052B:00	Cold Start Intake A Camshaft Position Timing Over-Retarded (Bank 1): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P052C:00	Cold Start Intake A Camshaft Position Timing Over-Advanced (Bank 2): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P052D:00	Cold Start Intake A Camshaft Position Timing Over-Retarded (Bank 2): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P054A:00	Cold Start Exhaust B Camshaft Position Timing Over-Advanced (Bank 1): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P054B:00	Cold Start Exhaust B Camshaft Position Timing Over-Retarded (Bank 1): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P054C:00	Cold Start Exhaust B Camshaft Position Timing Over-Advanced (Bank 2): No Sub Type Information	GO to Pinpoint Test HK
PCM (powertrain control module)	P054D:00	Cold Start Exhaust B Camshaft Position Timing Over-Retarded (Bank 2): No Sub Type Information	GO to Pinpoint Test HK

Global Customer Symptom Code (GCSC) Chart

Diagnostics in this manual assume a certain skill level and knowledge of Ford-specific diagnostic practices.

REFER to: Diagnostic Methods

(100-00 General Information, Description and Operation).

Global Customer Symptom Code Chart

Customer Symptom	Action
Start/Run/Move > Running > Failed Emissions Testing > Catalyst	GO to Pinpoint Test DR

Driving Performance > Engine Surge > Acceleration > Always	GO to Pinpoint Test HK
Driving Performance > Engine Surge > Cruise/ Steady Speed > Always	GO to Pinpoint Test HK
Driving Performance > Engine Surge > Deceleration > Always	GO to Pinpoint Test HK

Pinpoint Tests

PINPOINT TEST DR: CAMSHAFT POSITION (CMP) SENSOR

Normal Operation and Fault Conditions

Refer to the DTC (diagnostic trouble code) Fault Trigger Conditions.

DTC Fault Trigger Conditions

DTC (diagnostic trouble code)	Description	Fault Trigger Condition
PCM (powertrain control module) P0340:00	Camshaft Position Sensor 'A' Circuit (Bank 1 or single sensor): No Sub Type Information	Sets when the PCM (powertrain control module) detects the CMP (camshaft position) bank 1, sensor 1, circuit signal cannot be detected. Harness routing, harness alterations, incorrect shielding, or electrical interference from other systems may have an intermittent impact on the CMP (camshaft position) signal. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT (variable camshaft timing) phasers.
PCM (powertrain control module) P0344:00	Camshaft Position Sensor 'A' Circuit Intermittent (Bank 1 or single sensor): No Sub Type Information	Sets when the PCM (powertrain control module) detects the CMP (camshaft position) bank 1, sensor 1, circuit signal is intermittent. Harness routing, harness alterations, incorrect shielding, or electrical interference from other systems may have an intermittent impact on the CMP (camshaft position) signal. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT (variable camshaft timing) phasers.

module) P0369:00	1): No Sub Type Information	the CMP (camshaft position) sensor signal. Check for a camshaft position sensor trigger wheel alignment concern and a damaged mechanical vacuum pump. Make sure the mechanical vacuum pump oil feed hole is not restricted. Repair as necessary. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT (variable camshaft timing) phasers.
PCM (powertrain control module) P0390:00	Camshaft Position Sensor 'B' Circuit (Bank 2): No Sub Type Information	Sets when the PCM (powertrain control module) detects the CMP (camshaft position) bank 2, sensor 2 circuit signal can not be detected. Harness routing, harness alterations, incorrect shielding, or electrical interference from other systems may have an intermittent impact on the CMP (camshaft position) sensor signal. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT (variable camshaft timing) phasers
PCM (powertrain control module) P0394:00	Camshaft Position Sensor 'B' Circuit Intermittent (Bank 2): No Sub Type Information	Sets when the PCM (powertrain control module) detects the CMP (camshaft position) bank 2, sensor 2 circuit signal is intermittent. Harness routing, harness alterations, incorrect shielding, or electrical interference from other systems may have an intermittent impact on the CMP (camshaft position) sensor signal. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT (variable camshaft timing) phasers

Possible Sources

- Radio frequency interference or electromagnetic interference
- CMP (camshaft position) circuitry concern
- Oil flow restriction
- Mechanical vacuum pump
- Camshaft phaser and sprocket
- Camshaft timing
- Camshaft position sensor alignment

		concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P0012:00	'A' Camshaft Position Timing - Over-Retarded (Bank 1): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in a retarded position, indicating the VCT (variable camshaft timing) position is overretarded. This DTC (diagnostic trouble code) may be accompanied by other Diagnostic Trouble Codes (DTCs). Diagnose all CMP (camshaft position) sensor Diagnostic Trouble Codes (DTCs) first. If no CMP (camshaft position) sensor related Diagnostic Trouble Codes (DTCs) are present, continue to follow diagnosis for this DTC (diagnostic trouble code). This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P0013:00	'B' Camshaft Position Actuator 'A' Control Circuit/Open Bank 1: No Sub Type Information	Sets when PCM (powertrain control module) detects a low or high voltage on the VCT (variable camshaft timing) bank 1, solenoid 2 circuit or if the voltage exceeds a calibrated limit for a calibrated amount of time.
PCM (powertrain control module) P0014:00	'B' Camshaft Position Timing - Over-Advanced (Bank 1): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in an advanced position, indicating the VCT (variable camshaft timing) position is overadvanced. This DTC (diagnostic trouble code) may be accompanied by other Diagnostic Trouble Codes (DTCs). Diagnose all CMP (camshaft position) sensor Diagnostic Trouble Codes (DTCs) first. If no CMP (camshaft position) sensor related Diagnostic Trouble Codes (DTCs) are present, continue to follow diagnosis for this DTC (diagnostic trouble code). This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to

	No Sub Type Information	Trouble Codes (DTCs). Diagnose all CMP (camshaft position) sensor Diagnostic Trouble Codes (DTCs) first. If no CMP (camshaft position) sensor related Diagnostic Trouble Codes (DTCs) are present, continue to follow diagnosis for this DTC (diagnostic trouble code). This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P0018:00	Crankshaft Position - Camshaft Position Correlation - Bank 2 Sensor A: No Sub Type Information	Sets when PCM (powertrain control module) detects a misalignment between the camshaft and crankshaft. This indicates the misalignment is 1 tooth or greater. This DTC (diagnostic trouble code) can also set due to VCT (variable camshaft timing) system concerns (oil contamination or VCT (variable camshaft timing) solenoid stuck). This DTC (diagnostic trouble code) may be accompanied by other Diagnostic Trouble Codes (DTCs). Diagnose all CMP (camshaft position) sensor Diagnostic Trouble Codes (DTCs) first. If no CMP (camshaft position) sensor related Diagnostic Trouble Codes (DTCs) are present, continue to follow diagnosis for this DTC (diagnostic trouble code). This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P0019:00	Crankshaft Position - Camshaft Position Correlation - Bank 2 Sensor B: No Sub Type Information	Sets when PCM (powertrain control module) detects a misalignment between the camshaft and crankshaft. This indicates the misalignment is 1 tooth or greater. This DTC (diagnostic trouble code) can also set due to VCT (variable camshaft timing) system concerns (oil contamination or VCT (variable camshaft timing) solenoid stuck). This DTC (diagnostic trouble code) may be accompanied by other Diagnostic Trouble Codes (DTCs). Diagnose all CMP (camshaft position) sensor Diagnostic Trouble Codes (DTCs) first. If no CMP (camshaft position) sensor related Diagnostic Trouble Codes (DTCs) are present, continue to follow diagnosis for this DTC (diagnostic trouble code). This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to

the engine oil pressure or engine timing. Refer to the appropriate 303-

		check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P0023:00	'B' Camshaft Position Actuator 'A' Control Circuit/Open Bank 2: No Sub Type Information	Sets when PCM (powertrain control module) detects the voltage exceeds a calibrated limit for a calibrated amount of time, indicating a low or high voltage from the VCT (variable camshaft timing) bank 2 solenoid 2 circuit.
PCM (powertrain control module) P0024:00	'B' Camshaft Position Timing - Over-Advanced (Bank 2): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in an advanced position, indicating the VCT (variable camshaft timing) position is overadvanced. This DTC (diagnostic trouble code) may be accompanied by other Diagnostic Trouble Codes (DTCs). Diagnose all CMP (camshaft position) sensor Diagnostic Trouble Codes (DTCs) first. If no CMP (camshaft position) sensor related Diagnostic Trouble Codes (DTCs) are present, continue to follow diagnosis for this DTC (diagnostic trouble code). This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P0025:00	'B' Camshaft Position Timing - Over-Retarded (Bank 2): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in a retarded position, indicating the VCT (variable camshaft timing) position is overretarded. This DTC (diagnostic trouble code) may be accompanied by other Diagnostic Trouble Codes (DTCs). Diagnose all CMP (camshaft position) sensor Diagnostic Trouble Codes (DTCs) first. If no CMP (camshaft position) sensor related Diagnostic Trouble Codes (DTCs) are present, continue to follow diagnosis for this DTC (diagnostic trouble code). This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.

PCM (powertrain control module) P054A:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Advanced (Bank 1): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in an advanced position, indicating the VCT (variable camshaft timing) position is overadvanced during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P054B:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Retarded (Bank 1): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in a retarded position, indicating the VCT (variable camshaft timing) position is overretarded during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P054C:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Advanced (Bank 2): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in an advanced position, indicating the VCT (variable camshaft timing) position is overadvanced during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P054D:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Retarded (Bank 2): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in a retarded position, indicating the VCT (variable camshaft timing) position is overretarded during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.