

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2019 Ford Police Interceptor Utility Service and Repair Manual

Go to manual page

PCM (powertrain control module) P054A:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Advanced (Bank 1): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in an advanced position, indicating the VCT (variable camshaft timing) position is overadvanced during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P054B:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Retarded (Bank 1): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in a retarded position, indicating the VCT (variable camshaft timing) position is overretarded during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P054C:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Advanced (Bank 2): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in an advanced position, indicating the VCT (variable camshaft timing) position is overadvanced during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.
PCM (powertrain control module) P054D:00	Cold Start Exhaust (B) Camshaft Position Timing Over-Retarded (Bank 2): No Sub Type Information	Sets when PCM (powertrain control module) detects the camshaft timing exceeds a maximum calibrated value or remains in a retarded position, indicating the VCT (variable camshaft timing) position is overretarded during cold start up. This DTC (diagnostic trouble code) is a functional check of the VCT (variable camshaft timing) unit. Diagnose any base engine concerns related to the engine oil pressure or engine timing. Refer to the appropriate 303-00 section, Engine System, Oil Pressure Test, to check the engine oil pressure. Refer to the appropriate 303-01 section, Engine, to check the engine timing and VCT phasers.

Camshaft Position (CMP) Sensor

303-14B Electronic Engine Controls - 3.3L Duratec-V6	2022 F-150
Removal and Installation	Procedure revision date: 05/28/2020

Camshaft Position (CMP) Sensor


Removal

Camshaft Position (CMP) Bank 1 Sensor 1 and Bank 1 sensor 2

NOTE

Removal steps in this procedure may contain installation details.

- 1. Remove the RH (right-hand) fender splash shield. Refer to: Fender Splash Shield
- 2. Disconnect the transmission wiring harness retainers from the stud bolts.




4. • Disconnect the CMP (camshaft position) sensor electrical connector and remove the retainer and the CMP (camshaft position) sensor.

Torque: 89 lb.in (10 Nm)

• Disconnect the CMP (camshaft position) sensor electrical connector and remove the retainer and the CMP (camshaft position) sensor.

Torque: 89 lb.in (10 Nm)




Installation

NOTE

Before installation, lubricate the CMP (camshaft position) sensor O-ring seal with clean engine oil.

1. To install, reverse the removal procedure.


Copyright © Ford Motor Company



Catalyst Monitor Bank 1 Sensor 1

- 3. Disconnect the electrical connector and remove the harness retainer.
 - Apply penetrating oil to sensor, using the special tool remove the Catalyst monitor sensor.

Use Special Service Tool: 303-476 (T94P-9472-A) Socket, Exhaust Gas Oxygen Sensor **Material**: Motorcraft® Penetrating and Lock Lubricant / XL-1



Installation

Catalyst Monitor Bank 2 sensor 1


1. • Apply anti-seize to thread of sensor, using special tool install the Catalyst monitor sensor.

Use Special Service Tool: 303-476 (T94P-9472-A) Socket, Exhaust Gas Oxygen Sensor

Material: Motorcraft® High Temperature Nickel Anti-Seize Lubricant / XL-2

Torque: 35 lb.ft (48 Nm)


• Install the harness retainer and connect the electrical connector.



All sensors

3. If equipped, install the underbody shield.

Torque: 71 lb.in (8 Nm)



Crankshaft Position (CKP) Sensor

303-14B Electronic Engine Controls - 3.3L Duratec-V6	2022 F-150
Removal and Installation	Procedure revision date: 05/28/2020

Crankshaft Position (CKP) Sensor

Removal

NOTE


Removal steps in this procedure may contain installation details.

1. With the vehicle in NEUTRAL, position it on a hoist.

Refer to: Jacking and Lifting - Overview(100-02 Jacking and Lifting, Description and Operation).

- 2. If equipped, remove the bolts.
 - Release the retainer and remove the transmission housing cover.

Torque: 71 lb.in (8 Nm)



4. NOTE

Vehicles come with an underbody shield or a skid plate.

If equipped, remove the bolts and the skid plate.

Torque: 30 lb.ft (40 Nm)