

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

Mazda CX 5 2021 Manual & Service Workshop Guide

Go to manual page

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between front body control module (FBCM) and connectors C-55,C-54
- Connectors C-55,C-54 malfunction
- CAN circuit in front body control module (FBCM) malfunction



- · Adaptive front lighting system (AFS) control module / auto leveling control module / turn light unit connector
- Connectors C-55,C-54
- Wiring harness between adaptive front lighting system (AFS) control module / auto leveling control module terminal A and connector C-55 (type A)
- Wiring harness between adaptive front lighting system (AFS) control module / auto leveling control module terminal B and connector C-54 (type A)
- Wiring harness between adaptive front lighting system (AFS) control module / auto leveling control module / turn light unit terminal L and connector C-55 (type B)
- Wiring harness between adaptive front lighting system (AFS) control module / auto leveling control module / turn light unit terminal M and connector C-54 (type B)
- Adaptive front lighting system (AFS) control module / auto leveling control module / turn light unit

Possible cause

I

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connectors C-55,C-54 and connector C-08
- Open circuit in wiring harness between connector C-08 and connector C-24
- Open circuit in wiring harness between connector C-24 and connector C-74
- Connectors C-55, C-54 malfunction
- Connector C-08 malfunction
- Connector C-24 malfunction
- Connector C-74 malfunction

- Wiring harness between power liftgate (PLG) control module terminal 1B and connector C-74
- Wiring harness between power liftgate (PLG) control module terminal 1A and connector C-74
- Power liftgate (PLG) control module

K

SKYACTIV-D 2.2

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connector C-74 and connector C-24
- Open circuit in wiring harness between connector C-24 and connector C-87
- Connector C-74 malfunction
- Connector C-24 malfunction
- Connector C-87 malfunction



Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- NOx sensor No.1 power supply voltage or body ground malfunction
- Open circuit in wiring harness between NOx sensor No.1 and connector C-84
- Open circuit in wiring harness between connector C-84 and connector C-87
- Connector C-84 malfunction
- Connector C-87 malfunction
- NOx sensor No.1 malfunction



- Connector C-87
- Wiring harness between NOx sensor No.2 terminal B and connector C-84
- Wiring harness between NOx sensor No.2 terminal C and connector C-84
- Wiring harness between connector C-84 and connector C-87
- NOx sensor No.2

Ν

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- PM sensor power supply voltage or body ground malfunction
- Open circuit in wiring harness between PM sensor and connector C-84
- Open circuit in wiring harness between connector C-84 and connector C-87
- Connector C-84 malfunction
- Connector C-87 malfunction
- PM sensor malfunction

- Wiring harness between dosing control unit terminal BK and connector C-87
- Wiring harness between dosing control unit terminal BL and connector C-87
- Dosing control unit

Р

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connector C-87 and connector C-71
- Connector C-87 malfunction
- Connector C-71 malfunction



- Wiring harness between audio amplifier terminal 2L and connector C-71
- Wiring harness between audio amplifier terminal 2N and connector C-71
- Audio amplifier

R

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Electric parking brake control module power supply voltage or body ground malfunction
- Open circuit in wiring harness between electric parking brake control module and connector C-71
- Connector C-71 malfunction
- Electric parking brake control module malfunction



- Wiring harness between AWD control module terminal G and connector C-71
- Wiring harness between AWD control module terminal H and connector C-71
- AWD control module

Т

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connector C-71 and connectors C-72, C-73
- Connector C-71 malfunction
- Connectors C-72, C-73 malfunction





- Connectors C-72, C-73
- Wiring harness between position memory control module terminal 1C and connector C-31
- Wiring harness between position memory control module terminal 1E and connector C-31
- Wiring harness between connector C-31 and connectors C-72, C-73
- Position memory control module

٧

With forward sensing camera (FSC)

Possible cause

- Connector terminal disconnection, poor contact, damage, deformation, corrosion
- Open circuit in wiring harness between connectors C-72, C-73 and connector C-16
- Open circuit in wiring harness between connector C-16 and connector C-19
- Open circuit in wiring harness between connector C-19 and branch A
- Connectors C-72, C-73 malfunction
- Connector C-16 malfunction
- Connector C-19 malfunction

