

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2021 Nissan NV2500 HD Service and Repair Manual

Go to manual page

1. CHECK CONNECTOR

- 1. Turn the power switch OFF.
- 2. Check the terminals and connectors of the side radar front LH/RH for damage, bend and short (unit side and connector side).

Is the inspection result normal?

YES>>

GO TO 2.

NO>>

Repair the terminal or connector.

2. CHECK CONTINUITY OF RIGHT/LEFT SWITCHING SIGNAL CIRCUIT

- 1. Disconnect side radar front LH/RH connector.
- 2. Check continuity between side radar front LH/RH harness connector and ground.

Side radar f	ront RH		Continuity	
Connector	Terminal	Ground	Community	
E158	7		Yes	

Is the inspection result normal?

YES>>

Inspection End.

NO>>

Repair harness or connector.

DTC DETECTION LOGIC

DTC		CONSULT screen terms (Trouble diagnosis content)	DTC detection condition	
C2591	81	BCM 1 (Body control module)	Diagnosis condition	When vehicle is READYWhen AEB system is ON
G2551	C2551 01		Signal (terminal)	CAN communication signal
		Threshold	If the BCM is malfunction	
			Diagnosis delay time	2 seconds or more

POSSIBLE CAUSE

BCM

FAIL-SAFE

The following systems are canceled.

- Vehicle-to-vehicle distance control mode*1
- Conventional (fixed speed) cruise control mode*1
- Steering wheel assistance function*1
- Vehicle speed & vehicle-to-vehicle control function*2
- Lane keep function*2,3
- Lane keep function*2,4
- Lane change support function*2
- Overtaking support function*2
- Route driving support function*2
- AEB
- RAB
- I-FCW
- *1: With ProPILOT Assist, Without ProPILOT Assist 2.0
- *2: With ProPILOT Assist 2.0
- *3: ProPILOT Assist 2.0 display is green
- *4: ProPILOT Assist 2.0 display is blue

CONFIRMATION PROCEDURE

1. CHECK DTC PRIORITY

If DTC "C2591-81" is displayed with Network-DTC, first diagnose the Network-DTC.

Is applicable DTC detected?

YES >>

Perform diagnosis of applicable. Refer to <u>DTC Index</u>.

NO >>

GO TO 2.

2. PERFORM DTC CONFIRMATION PROCEDURE

- 1. Set the vehicle to READY.
- 2. Turn the AEB system ON, and then wait for 2 seconds or more.
- 3. Perform "All DTC Reading" with CONSULT.
- 4. Check if the "C2591-81" is detected as the current malfunction in self-diagnosis results of "LASER/RADAR".

Is "C2591-81" detected as the current malfunction?

YES >>

Refer to DTC Diagnosis Procedure.

NO-1 >>

To check malfunction symptom before repair:Refer to Intermittent Incident.

NO-2 >>

Confirmation after repair: INSPECTION END

1. CHECK DTC PRIORITY

If DTC "C2591-81" is displayed with Network-DTC, first diagnose the Network-DTC.

Is applicable DTC detected?

YES >>

Perform diagnosis of applicable. Refer to <u>DTC Index</u>.

NO >>

GO TO 2.

2. CHECK BCM SELF-DIAGNOSIS RESULTS

Check if any DTC is detected in "Self Diagnostic Result" of "BCM".

Is any DTC detected?

YES >>

Perform diagnosis on the detected DTC and repair or replace the malfunctioning parts. Refer to DTC Index.

NO >>

Replace the distance sensor. Refer to Removal and Installation.

DTC DETECTION LOGIC

DTC CONSULT screen terms (Trouble diagnosis content)			DTC detection condition	
C2591	82	BCM 32 (Body control module)	Diagnosis condition	When vehicle is READYWhen AEB system is ON
G2331	C2391 62		Signal (terminal)	CAN communication signal
		Threshold	If the BCM is malfunction	
			Diagnosis delay time	2 seconds or more

POSSIBLE CAUSE

BCM

FAIL-SAFE

The following systems are canceled.

- Vehicle-to-vehicle distance control mode*1
- Conventional (fixed speed) cruise control mode*1
- Steering wheel assistance function*1
- Vehicle speed & vehicle-to-vehicle control function*2
- Lane keep function*2,3
- Lane keep function*2,4
- Lane change support function*2
- Overtaking support function*2
- Route driving support function*2
- AEB
- RAB
- I-FCW
- *1: With ProPILOT Assist, Without ProPILOT Assist 2.0
- *2: With ProPILOT Assist 2.0
- *3: ProPILOT Assist 2.0 display is green
- *4: ProPILOT Assist 2.0 display is blue

CONFIRMATION PROCEDURE

1. CHECK DTC PRIORITY

If DTC "C2591-82" is displayed with Network-DTC, first diagnose the Network-DTC.

Is applicable DTC detected?

YES >>

Perform diagnosis of applicable. Refer to <u>DTC Index</u>.

NO >>

GO TO 2.

2. PERFORM DTC CONFIRMATION PROCEDURE

- 1. Set the vehicle to READY.
- 2. Turn the AEB system ON.
- 3. Perform "All DTC Reading" with CONSULT.
- 4. Check if the "C2591-82" is detected as the current malfunction in self-diagnosis results of "LASER/RADAR".

Is "C2591-82" detected as the current malfunction?

YES >>

Refer to DTC Diagnosis Procedure.

NO-1 >>

To check malfunction symptom before repair: Refer to Intermittent Incident.

NO-2 >>

Confirmation after repair: INSPECTION END

1. CHECK DTC PRIORITY

If DTC "C2591-82" is displayed with Network-DTC, first diagnose the Network-DTC.

Is applicable DTC detected?

YES >>

Perform diagnosis of applicable. Refer to <u>DTC Index</u>.

NO >>

GO TO 2.

2. CHECK BCM SELF-DIAGNOSIS RESULTS

Check if any DTC is detected in "Self Diagnostic Result" of "BCM".

Is any DTC detected?

YES >>

Perform diagnosis on the detected DTC and repair or replace the malfunctioning parts. Refer to DTC Index.

NO >>

Replace the distance sensor. Refer to Removal and Installation.

DTC DETECTION LOGIC

DTC		CONSULT screen terms (Trouble diagnosis content)	DTC detection condition	
C2591 8	86	BCM	Diagnosis condition	When vehicle is READYWhen AEB system is ON
G2551	G2531 00		Signal (terminal)	CAN communication signal
			Threshold	If the BCM is malfunction
			Diagnosis delay time	2 seconds or more

POSSIBLE CAUSE

BCM

FAIL-SAFE

The following systems are canceled.

- Vehicle-to-vehicle distance control mode*1
- Conventional (fixed speed) cruise control mode*1
- Steering wheel assistance function*1
- Vehicle speed & vehicle-to-vehicle control function*2
- Lane keep function*2,3
- Lane keep function*2,4
- Lane change support function*2
- Overtaking support function*2
- Route driving support function*2
- AEB
- RAB
- I-FCW
- *1: With ProPILOT Assist, Without ProPILOT Assist 2.0
- *2: With ProPILOT Assist 2.0
- *3: ProPILOT Assist 2.0 display is green
- *4: ProPILOT Assist 2.0 display is blue

CONFIRMATION PROCEDURE

1. CHECK DTC PRIORITY

If DTC "C2591-86" is displayed with Network-DTC, first diagnose the Network-DTC.

Is applicable DTC detected?

YES >>

Perform diagnosis of applicable. Refer to <u>DTC Index</u>.

NO >>

GO TO 2.

2. PERFORM DTC CONFIRMATION PROCEDURE

- 1. Set the vehicle to READY.
- 2. Turn the AEB system ON, and then wait for 2 seconds or more.
- 3. Perform "All DTC Reading" with CONSULT.
- 4. Check if the "C2591-86" is detected as the current malfunction in self-diagnosis results of "LASER/RADAR".

Is "C2591-86" detected as the current malfunction?

YES >>

Refer to DTC Diagnosis Procedure.

NO-1 >>

To check malfunction symptom before repair: Refer to Intermittent Incident.

NO-2 >>

Confirmation after repair: INSPECTION END