

# Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.


## **1980 CHEVROLET Camaro OEM Service and Repair Workshop Manual**

[Go to manual page](#)

YOUR CURRENT VEHICLE

# Rear Bumper Fascia Molding Replacement

## Rear Bumper Fascia Molding Replacement



### Rear Bumper Fascia Molding Replacement

Callout	Component Name
<b>Preliminary Procedure</b> Open and support the rear liftgate/rear compartment lid.	
1	Rear Bumper Fascia Molding <b>Procedure</b>



YOUR CURRENT VEHICLE


## Rear Bumper Fascia Outer Support Replacement

### Rear Bumper Fascia Outer Support Replacement (Left Side)

#### Removal Procedure

1. Rear Wheelhouse Liner »Remove— [Rear Wheelhouse Liner Replacement](#).






3.

Transmission Fluid Auxiliary Cooler Bracket Bolt Remove[2x]





1. Rear Bumper Fascia Outer Support Bracket (2) »Install

2. **CAUTION**

**Caution**

Refer to [Fastener Caution](#).

Rear Bumper Fascia Outer Support Nut (1)Install and tighten5N·m(44 lb in)