

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.


1995 CHEVROLET Cavalier OEM Service and Repair Workshop Manual

[Go to manual page](#)

YOUR CURRENT VEHICLE

Instrument Panel Knee Bolster Replacement

Instrument Panel Knee Bolster Replacement




Instrument Panel Knee Bolster Replacement

Callout	Component Name
Preliminary Procedure	
1. Remove the left front floor console trim plate. Refer to Front Floor Console Trim Plate Replacement	
2. Remove the left front side door sill garnish molding. Refer to Front Side Door Sill Garnish Molding Replacement .	

YOUR CURRENT VEHICLE

Instrument Panel Lower Center Trim Panel Replacement

Instrument Panel Lower Center Trim Panel Replacement




Instrument Panel Lower Center Trim Panel Replacement

Callout	Component Name
Preliminary Procedure Remove the right instrument panel assist handle. Refer to Instrument Panel Assist Handle Replacement .	
1	Instrument Panel Lower Center Trim Panel Procedure

YOUR CURRENT VEHICLE

Instrument Panel Lower Trim Panel Replacement

Instrument Panel Lower Trim Panel Replacement




Instrument Panel Lower Trim Panel Replacement

Callout	Component Name
Preliminary Procedures	
1.	Remove the instrument panel lower center trim panel. Refer to Instrument Panel Lower Center Trim Panel Replacement .
2.	Remove the front floor lower console. Refer to Front Floor Lower Console Replacement .

YOUR CURRENT VEHICLE

Instrument Panel Molding Replacement

Instrument Panel Molding Replacement



Instrument Panel Molding Replacement

Callout	Component Name
<p>Preliminary Procedure</p> <p>1. Remove the instrument panel center upper molding. Refer to Instrument Panel Center Upper Molding Replacement.</p> <p>2. Remove the instrument panel lower center trim panel. Refer to Instrument Panel Lower Center Trim Panel Replacement.</p>	