

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2006 CHEVROLET TrailBlazer SS OEM Service and Repair Workshop Manual

[Go to manual page](#)

Callout	Component Name
Prying against the folding top rails could result in damage to parts.	
NOTE	
Note Manual operation of the folding top cannot be attempted for 5 minutes from the last time the folding top button was pressed. This will allow the hydraulic pressure to bleed off.	
Preliminary Procedures 1. Place the folding top to mid-position. 2. Remove the folding top cover enough to gain access to the bow. Refer to Folding Top Cover Replacement .	
1	<div>Folding Top Bow Screw (Qty: 6)</div> <div>CAUTION</div> <div>Caution Refer to Fastener Caution.</div> <div>Tighten 3 N·m (27 lb in)</div>
2	<div>Folding Top Number 2 Bow</div> <div>NOTE</div> <div>Note Slide bow from either side of the vehicle.</div>

Callout	Component Name
Prying against the folding top rails could result in damage to parts.	
NOTE	
Note Manual operation of the folding top cannot be attempted for 5 minutes from the last time the folding top button was pressed. This will allow the hydraulic pressure to bleed off.	
Preliminary Procedures 1. Place the folding top to mid-position. 2. Remove the folding top cover enough to gain access to the bow. Refer to Folding Top Cover Replacement .	
1	<div>Folding Top Bow Screw (Qty: 6)</div> <div>CAUTION</div> <div>Caution Refer to Fastener Caution.</div> <div>Tighten 3 N·m (27 lb in)</div>
2	<div>Folding Top Number 3 Bow</div> <div>NOTE</div> <div>Note Slide bow from either side of the vehicle.</div>

Callout	Component Name
Prying against the folding top rails could result in damage to parts.	
NOTE	
Note Manual operation of the folding top cannot be attempted for 5 minutes from the last time the folding top button was pressed. This will allow the hydraulic pressure to bleed off.	
Preliminary Procedures 1. Place the folding top to mid-position. 2. Remove the folding top cover enough to gain access to the bow. Refer to Folding Top Cover Replacement .	
1	<div>Folding Top Bow Screw (Qty: 6)</div> <div>CAUTION</div> <div>Caution Refer to Fastener Caution.</div> <div>Tighten 3 N·m (27 lb in)</div>
2	<div>Folding Top Number 4 Bow</div> <div>NOTE</div> <div>Note Slide bow from either side of the vehicle.</div>

Callout	Component Name
	<p>Prying against the folding top rails could result in damage to parts.</p>
<div>NOTE</div>	
<p>Note</p> <p>Manual operation of the folding top cannot be attempted for 5 minutes from the last time the folding top button was pressed. This will allow the hydraulic pressure to bleed off.</p>	
<p>Preliminary Procedures</p> <ol style="list-style-type: none"> 1. Position the folding top with the number 5 bow into mid-position. 2. Remove the folding top rear weatherstrip retainer. Refer to Roof Retractable Rear Panel Weatherstrip Replacement. 3. Remove the folding top cover from the folding top number 5 bow by pulling seam from number 5 bow groove. 	
1	<p>Folding Top Number 5 Bow Screw (Qty: 10)</p> <div>CAUTION</div> <p>Caution</p> <p>Refer to Fastener Caution.</p> <div> <div>Tighten</div> <div>10 N·m (89 lb in)</div> </div>
2	<p>Folding Top Number 5 Bow</p> <div>NOTE</div> <p>Note</p> <p>Water test the vehicle to ensure no leaks.</p>