

# Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

1994 CHEVROLET Corvette C4 Convertible OEM Service and Repair Workshop Manual

Go to manual page

X50A Fuse Block - Underhood Top View **G202** G202 G202 G202, G305 **G201** G201 G201 G201, G203 **G100** G100 G100, G107, and G108 G100 X50A X50A Fuse Block - Underhood Right Side of Engine Compartment Components X50A Fuse Block - Underhood X1 X50A Fuse Block - Underhood X2 X50A Fuse Block - Underhood X3 X50A Fuse Block - Underhood X4 X50A Fuse Block - Underhood X5 X50A Fuse Block - Underhood X6 X50A Fuse Block - Underhood X6 (Starter Motor Harness) KR147 KR147 Instrument Panel Compartment Door Unlatch Actuator Relay M91 M91 Instrument Panel Compartment Door Unlatch Actuator Front of Instrument Panel Components M91 Instrument Panel Compartment Door Unlatch Actuator K9 K9 Body Control Module Right Front of Passenger Compartment Components **K9 Body Control Module X1** K9 Body Control Module X2 K9 Body Control Module X3 K9 Body Control Module X4 **K9 Body Control Module X5** K9 Body Control Module X6

## **Fastener Specifications**

#### **Fastener Specifications**

### **Reusable Threaded Fastener Tightening Specifications**

#### NOTE

# Note All fasteners listed in this table can be reused after removal.

Application	Specification
	Metric (English)
Front Floor Console Armrest Bolt	2.5N·m(22 lb in)
Front Floor Console Armrest Latch Screw	1.5N·m(13 lb in)
Front Floor Console Compartment Nut	4.7N·m(42 lb in)
Front Floor Console Nut	9N·m(80 lb in)
Front Floor Console Retainer Bolt	9N·m(80 lb in)
Front Floor Console Trim Plate Bolt	2.5N·m(22 lb in)
Instrument Panel Accessory Bracket to the Instrument Panel Lower Bracket	2.5N·m(22 lb in)
Instrument Panel Accessory Bracket to the Instrument Panel	9N·m(80 lb in)
Instrument Panel Assist Handle Bolt	1.9N·m(17 lb in)

Instrument Panel Trim Plate Bolt	2.5N·m(22 lb in)
Power Brake Booster Nut	23N·m(17 lb ft)
Steering Column Bracket Bolt	9N·m(80 lb in)



Callout	Component Name
	CAUTION
	Caution  Refer to Fastener Caution.
	Tighten 4.7 N·m (42 lb in)
2	Front Floor Console Armrest Hinge