


Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2002 VOLVO C70 Convertible OEM Service and Repair Workshop Manual

Go to manual page



WARNING: Wait for the specified time at the specified temperature before moving the car.

REAR WINDOW TAILGATE > REAR WINDOW TAILGATE [2018-2022] > INSTALLATION


Install spoiler rear. Refer to: SPOILER REAR Install wiper motor, rear. Refer to: WIPER MOTOR, REAR To install, reverse the removal procedure.

WINDSHIELD > WINDSHIELD [2021-2022, E400V6] > REMOVAL


NOTE: Make sure that the vehicle is standing on a level surface.

See information about bonded windows, general safety information. Refer to: BONDED WINDOW, GENERAL SAFETY INFORMATION

See information about bonded windows, general information. Refer to: BONDED WINDOW GENERAL, INFORMATION




Courtesy of VOLVO CARS CORPORATION




Courtesy of VOLVO CARS CORPORATION

CAUTION: Make sure that the components are protected.




Courtesy of VOLVO CARS CORPORATION


NOTE: If the primer is damaged, remove primer only along the side concerned, not all around the window.



Use: Activator, Wipe dry.



Courtesy of VOLVO CARS CORPORATION




WARNING: Wait for the specified time at the specified temperature before moving the car.

Install the following items:


- plenum cover. Refer to: PLENUM COVER
- inner rear view mirror. Refer to: INNER REAR VIEW MIRROR
- A-pillar trim panel. Refer to: A-PILLAR TRIM PANEL
- · rain and light sensor RLSM. Refer to: RAIN AND LIGHT SENSOR RLSM
- In-vehicle Humidity Sensor. Refer to: IN-VEHICLE HUMIDITY SENSOR
- trim strip, A-pillar. Refer to: A-PILLAR MOLDING
- forward looking camera (FLC). Refer to: FORWARD LOOKING CAMERA

Calibrate FLC2 according to: Diagnostics / Components / Control modules / Forward looking camera (FLC2) / Diagnostic sequences /Calibration of forward looking camera (FLC2)

WINDSHIELD > WINDSHIELD [2018-2022, B4204T18 | 2019-2022, B4204T47] > REMOVAL



Courtesy of VOLVO CARS CORPORATION



Courtesy of VOLVO CARS CORPORATION

CAUTION: Make sure that the components are protected.