

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.



2006 CHEVROLET Celta - 3 doors OEM Service and Repair Workshop Manual

[Go to manual page](#)

YOUR CURRENT VEHICLE

Mode Control Cam Actuator Replacement

Mode Control Cam Actuator Replacement




Mode Control Cam Actuator Replacement

Callout	Component Name
Preliminary Procedure Remove the instrument panel outer air outlet duct assembly. Refer to Instrument Panel Outer Air Outlet Duct Replacement .	
1	Mode Control Cam Actuator Fastener (Qty: 2)

YOUR CURRENT VEHICLE

Mode Control Cam Replacement

Mode Control Cam Replacement




Mode Control Cam Replacement

Callout	Component Name
<p>Preliminary Procedures</p> <p>1. Remove the mode control cam actuator. Refer to Mode Control Cam Actuator Replacement.</p> <p>2. Remove the left side window defogger outlet duct. Refer to Side Window Defogger Outlet Duct Replacement - Left Side.</p>	

YOUR CURRENT VEHICLE

Sun Load Temperature and Headlamp Automatic Control Ambient Light Sensor Replacement

Sun Load Temperature and Headlamp Automatic Control Ambient Light Sensor Replacement





Sun Load Temperature and Headlamp Automatic Control Ambient Light Sensor Replacement

Callout	Component Name
<p>Preliminary Procedure</p> <p>Remove the instrument panel upper trim panel cover. Refer to Instrument Panel Upper Trim Panel Cover Replacement.</p>	

YOUR CURRENT VEHICLE

Temperature Valve Actuator Replacement - Left Side

Temperature Valve Actuator Replacement - Left Side



Temperature Valve Actuator Replacement - Left Side

Call out	Component Name
<p>Preliminary Procedures</p> <p>1. Remove the steering column assembly. Refer to Steering Column Replacement.</p> <p>2. Remove the left front floor air outlet duct fasteners. Refer to Floor Front Air Outlet Duct Replacement - Left Side.</p>	