

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2020 Jeep GRAND CHEROKEE Service Manual

[Go to manual page](#)

YOUR CURRENT VEHICLE

SA433

SA433

HARNESS_CONNECTOR No:SA433		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	FRONT_END_MODULE
Repair Kit Part Number	Not Serviced	FRONT_END_MODULE
Part Description		FRONT_END_MODULE
Cavity Count	N/A	FRONT_END_MODULE
Location View	Location View	FRONT_END_MODULE

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
FRONT_END_MODULE					
1	A433	FUSED B(+)	RD	0.50	

YOUR CURRENT VEHICLE

SA92

SA92

HARNESS_CONNECTOR No:SA92		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	Steering_Wheel
Repair Kit Part Number	Not Serviced	Steering_Wheel
Part Description		Steering_Wheel
Cavity Count	N/A	Steering_Wheel
Location View	Location View	Steering_Wheel

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
Steering_Wheel					
1	A92	FUSED B(+)	RD	0.35	
2	A92	FUSED B(+)	RD	0.35	
3	A92	FUSED B(+)	RD	0.35	
4	A92	FUSED B(+)	RD	0.35	

YOUR CURRENT VEHICLE

SA971A

SA971A

HARNESS_CONNECTOR No:SA971A		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	IP
Repair Kit Part Number	Not Serviced	IP
Part Description		IP
Cavity Count	N/A	IP
Location View	Location View	IP

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
IP					
1	A971	FUSED B(+)	RD	0.35	

YOUR CURRENT VEHICLE

SC211A

SC211A

HARNESS_CONNECTOR No:SC211A		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	HVAC_Front
Repair Kit Part Number	Not Serviced	HVAC_Front
Part Description		HVAC_Front
Cavity Count	N/A	HVAC_Front
Location View	Location View	HVAC_Front

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
HVAC_Front					
1	C211	POWER SUPPLY	RD	0.50	
2	C211	POWER SUPPLY	RD	0.35	
3	C211	POWER SUPPLY	RD	0.35	
4	C211	POWER SUPPLY	RD	0.35	
5	C211	POWER SUPPLY	RD	0.35	

YOUR CURRENT VEHICLE

SC211C

SC211C

HARNESS_CONNECTOR No:SC211C		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	HVAC_MSM
Repair Kit Part Number	Not Serviced	HVAC_MSM
Part Description		HVAC_MSM
Cavity Count	N/A	HVAC_MSM
Location View	Location View	HVAC_MSM

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
HVAC_MSM					
1	C211	POWER SUPPLY	RD	0.50	
2	C211	POWER SUPPLY	RD	0.35	
3	C211	POWER SUPPLY	RD	0.35	

YOUR CURRENT VEHICLE

SC212B

SC212B

HARNESS_CONNECTOR No:SC212B		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	HVAC_Front
Repair Kit Part Number	Not Serviced	HVAC_Front
Part Description		HVAC_Front
Cavity Count	N/A	HVAC_Front
Location View	Location View	HVAC_Front

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
HVAC_Front					
1	C212	GROUND	BN	0.50	
2	C212	GROUND	BN	0.35	
3	C212	GROUND	BN	0.35	
4	C212	GROUND	BN	0.35	
5	C212	GROUND	BN	0.35	

Sample

YOUR CURRENT VEHICLE

SD282

SD282

HARNESS_CONNECTOR No:SD282		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	Body
Repair Kit Part Number	Not Serviced	Body
Part Description		Body
Cavity Count	N/A	Body
Location View	Location View	Body

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
Body					
1	D282	CAN FD (+)	VT	0.35	

YOUR CURRENT VEHICLE

SD283A

SD283A

HARNESS_CONNECTOR No:SD283A		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	DASH
Repair Kit Part Number	Not Serviced	DASH
Part Description		DASH
Cavity Count	N/A	DASH
Location View	Location View	DASH

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
DASH					
1	D283	CAN FD (-)	BG	0.35	