

Your Ultimate Source for OEM Repair Manuals

FactoryManuals.net is a great resource for anyone who wants to save money on repairs by doing their own work. The manuals provide detailed instructions and diagrams that make it easy to understand how to fix a vehicle.

2021 Jeep Compass Service and Repair Manual

Go to manual page

SP877

SP877

HARNESS_CONNECTOR No:SP877		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	SEAT_CUSHION_2ND_ROW
Repair Kit Part Number	Not Serviced	SEAT_CUSHION_2ND_ROW
Part Description		SEAT_CUSHION_2ND_ROW
Cavity Count	N/A	SEAT_CUSHION_2ND_ROW
Location View	Location View	SEAT_CUSHION_2ND_ROW

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option	
	SEAT_CUSHION_2ND_ROW					
1	P877	SENSOR RETURN	GN	0.35		

SP989A

SP989A

HARNESS_CONNECTOR	Option:Standard	
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	IP
Repair Kit Part Number	Not Serviced	IP
Part Description		IP
Cavity Count	N/A	IP
Location View	Location View	IP

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option	
	IP					
1	P989	SENSOR RETURN	BG	0.50		

Spu002

SPU002

HARNESS_CONNECTOR No:SPU002		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	Injector
Repair Kit Part Number	Not Serviced	Injector
Part Description		Injector
Cavity Count	N/A	Injector
Location View	Location View	Injector

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
	Injector				
1	F343	ASD RELAY OUTPUT	BN	1.0	

SR13

SR13

HARNESS_CONNECTOR	Option:Standard	
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	Body
Repair Kit Part Number	Not Serviced	Body
Part Description		Body
Cavity Count	N/A	Body
Location View	Location View	Body

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option	
	Body					
1	R13	SIGNAL	GN	0.35		

SR15

SR15

HARNESS_CONNECTOR	Option:Standard	
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	Body
Repair Kit Part Number	Not Serviced	Body
Part Description		Body
Cavity Count	N/A	Body
Location View	Location View	Body

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option	
	Body					
1 R15 SENSOR GROUND		GN	0.35			

SR2

SR2

HARNESS_CONNECTOR No:SR2		Option:Standard
Connector Details		Harness Family
Color	NA	
Part Number	AGV36375	HV_CHARGE_PORT_TO_IDCM
Repair Kit Part Number	Not Serviced	HV_CHARGE_PORT_TO_IDCM
Part Description		HV_CHARGE_PORT_TO_IDCM
Cavity Count	N/A	HV_CHARGE_PORT_TO_IDCM
Location View	Location View	HV_CHARGE_PORT_TO_IDCM

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
		HV_CHARGE_PORT_TO_IDCM			
1	G135	CHARGE TEMPERATURE INDICATOR RETURN	VT	1.5	
1	G235	HEV - CHARGE PORT TEMP SIGNAL	VT	1.5	

SR729C

SR729C

HARNESS_CONNECTOR No:SR729C		Option:Standard	
Connector Details		Harness Family	
Color	NA		
Part Number	AGV36375	SEAT_CUSHION_PASSENGER	
Repair Kit Part Number	Not Serviced	SEAT_CUSHION_PASSENGER	
Part Description		SEAT_CUSHION_PASSENGER	
Cavity Count	N/A	SEAT_CUSHION_PASSENGER	
Location View	Location View	SEAT_CUSHION_PASSENGER	


Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
SEAT_CUSHION_PASSENGER					
1	R729	SENSOR RETURN	GN	0.35	

ST762

ST762

HARNESS_CONNECTOR	Option:Standard	
Connector Details	Harness Family	
Color	NA	
Part Number	AGV36375	DASH
Repair Kit Part Number	Not Serviced	DASH
Part Description		DASH
Cavity Count	N/A	DASH
Location View	Location View	DASH

Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
DASH					
1	T762	CONTROL	DG	0.35	





Pin	Cicuit	Cicuit Function	Color	Gauge/Size	Option
STARTER_ GENERATOR					
1	A8	FUSED B(+)	RD	35.0	